## REMON. COR. 1-12, HOMER TWP. LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN	
MIDLAND COUNTY	
REMONUMENTATION & FTIE	
CONTROL OF THE PERSON AS A SECOND	1

12/28/2000 8:44:27 AM

SCOTT I. HAINES REGISTER OF DEEDS

Register of Deeds Stamp & File Number

For comers in <u>Midland</u> (County) Located in: Comer Code # 1. Public Land Survey 14N R 1E 1-12 SU<del>RVEY &</del> 2. Property Controlling REMONUMENTATION in Section Miscellaneous FEB 23 R Property in Sec. R 4. Lot No. , Recorded Plat SECTION


I, <u>RODNEY CLAYPOOL</u>, in a field survey on <u>July 13</u>, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- **I-12** 1/4 Corner common to Sections 34 and 35

5. Private Claims

Survey by Glo, 1830's, set post Survey by M. Hunter, 1957, 1962, 1965, 1967, found Survey by D. Whittier, 1964, 1975, found Survey by R. Strejc, 1973, found Survey by K. Surje, 1973, 1984, found 3/" pipe Survey by M. MacDonald, 1984, found 3/" pipe Survey by J. Jones, 1986, 1999, found 3/" pipe LCRC by P. Lapham, 1971, found 3/" pipe



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.
- 1/4 Corner common to Sections 34 and 35

Found ¾" pipe per surveys by M. Hunter, D. Whittier, P. Lapham, R. Strejc, M. MacDonald, J. Jones and LCRC by P. Lapham.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1/4 Corner common to Sections 34 and 35

Replaced pipe with 5/8" rod 3' long and brass cap stamped Midland Co. Remon Cor PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

N 10 Deg W, 17.74, nail in 6" Ash (new) Rec. 17.50 S 5 Deg W, 34.60, nail in 20" Cottonwood. Rec. 34.6 (8" Cottonwood) S 45 Deg W, 38.21, nail in 30" Cottonwood. Rec. 38.10 (18" Cottonwood) S 2 Deg E, 9.75, nail in 4" Ash. Rec. 9.75 N 85 Deg W, 6.08, nail in 8" Elm. Rec. 6.15 Corner is on eyeball centerline of road South and East

Signed by Rodrigan License No. 29241

Date 12.26.

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

F.A. 345 OF 1990 MIDLAND COUNTY

RODREY D. CLAYFOOL

LAND

29241

A THE VED LAND CORRECT 14/67/00 98