		ORNER RE						ΓE						
For Corners In: Midland (County)			orner Code #											
1. Public Land Survey	<u>T</u>	R												
Property Controlling in Section	S 4 T 14N	R_1W	4											
Miscellaneous     Property in Section	S 4 T 14N S T S T	R 1W R R R R R R R R R R R R R R R R R R				F	Ragist	er of D	eeds !	Stamn	& File	Numi	nar.	
4. Lot No:	Recorded Plat:			_ '							<u> </u>	NOM	<u> </u>	
5. Private Claims:					1 A 2 A	-é-		E F	6	H	J K			
I, <u>Craig W. McVean</u> , in a frequirements of PA 74, Min and 2 above were in conforthe current manual of sur Interior, Bureau of Land Macorner points mentioned in of the Michigan Board of established, re-established.	chigan PA of 1970, the cormance with regulations an vey instructions of the Unnagement or by a decree of lines 3, 4 and 5 above wer Land Surveyors or by	mer points ment of rules therefore ited States Dep of a Court of Law e in conformance of Decree of a	tioned in lines re as required partment of the v and/or that the ce with the rule Court of Lay	1 in ie ie	3 - 4 - 5 - 7 - 8 -	-7 -18- -19-		9 16		10	-11 -14 -23	12 13 24	-	
NOTE: Not more than 2 corners, all in the same town and rang be recorded on this certificate.					10	_30_	29	28	-	27	-26	25	1	
			40		11	-31-	32	33	+	1	-35	-36-	1	
A. Description of original	monument and accessor	ories and/or su	ibsequent re	toration	13 L		11						_	
<u>4</u> - None			5-1 Si -19 R	899 – CS et Post. 981 – Re L. Merry 169,98' –	SR – Dista cord y - Sh	nce I Surv	N-22.: ey – I	285, S 3, p.	-20.0 . 309	0 & 308	3		bbs.	
B. Description of corner	evidence found and/or π	nethod applied	l in restoring	or re-esta	ablish	ina c	corne	P4						
4 - NW 1/16 Corner Sec. 4 - Set 2" Alum. Cap on 5/8" x 34" long iron rebar at intersection of 1/16 lines per standard BLM procedure. The N 1/16 line being established by prorating to F.J. Gibbs 1899 dimensions on W. sec. line and N-S ¼ line.				5 – CN 1/16 Corner Sec. 4 – Dug 2' + dia. Area at calculated position but no evidence of Gibbs post was found in dry sandy soil. Set 2" Alum. Cap on 5/8" x 34" rebar by single proportion to Gibb's 1899 survey. Measured grid bearing and distance as follows; N0°37'39'E 1469.20' (1470.81' – FJG) to 'F1' and S0°37'39'W 1318.55 (1320' – FJG) to 'F2'. N86°20'W 9.14' from Cor. '5' to fd. ½" iron rod at corner of steel cable N & E. This ½" iron rod may be R. L. Merry's position but is too far out of position to be acceptable.										
C. Description of monum	ent for corner and acces	ssories establis	shed to perpe	etuate lo	cating	, the	positi	on of t	the co	rner:				
4 – Stamped 2" Alum. Ca Set Blue Carsonite P S36°E 17.05' to set N S88°W 23.61' to set N37°W 35.57' to set		n rebar aple Dak Oak	<u>5</u> - S S N N S S	tamped 2 et Blue 0 75°W 33 1°W 43.0 45°E 18.	2" Alu Carso 3.61' to 08' to 39' to	minu nite f o set set f set o set	Im ca Post v N & T N & T N & T	p on 5 vith loo T in S. in W. in NE	i/8" x c. tag side side side	34" lo 1' NV 12" V 16" W 12" C	ong iro V V. Pine V. Pine Dak	e	ar.	

Surveyor's Michigan License No.: 39088

Date:

N86°20'W 9.14' to Fd. 1/2" iron rod

OF MICHIGAN CRAIG W. McVEAN ROFESSIONAL SURVEYOR No. 39088 28, 1971 Noted May 14, 1975 Revised Jan. 1983 Revised Oct. 1995

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION