

Land Corner Recordation Certificate
Attachment B to 2018 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2018 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2018 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Greendale Twp.

Corner Type	Survey Township	Corner Code
Original Public Land Survey Corner	T 14N R 2W	F13
• MCL 54.202(g)	T R	
• MCL 54.262(g)	T R	
Property Controlling Corner	S T R	
• MCL 54.202(i)	S T R	
• MCL 54.262(h)	S T R	
	S 33 T 14N R 2W	Near F13
Protracted Public Land Survey Corner	T R	
• MCL 54.202(k)	T R	
• MCL 54.262(i)	T R	

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6			5		4		3		2		1		2
3														3
4	7			8		9		10		11		12		4
5														5
6	18			17		16		15		14		13		6
7														7
8	19			20		21		22		23		24		8
9														9
10	30			29		28		27		26		25		10
11														11
12	31			32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

F13 – Standard ¼ corner common to Sec. 33, T14N, R2W

- **1831** – R. Clark, Jr. – ¼ Sec. post - 1) Hemlock 8" N2°W 9 L.; 2) Hemlock 10" N78°E 15 L.
- **1912** – Alspaugh Drain – R. M. Hastings and H. L. McLean – Surveyors. "Thence same course [N88°W 32 Links S. of Sec. line] 40.30 Ch. across ¼ line Sec. 4 [N. line Sec. 4, T13N, R2W – Jasper Twp.]"
- **1980** – LCRC # 544 and Rec. Survey L. 3, p. 254 – T. J. Mueller (PS # 25861) – Set 'T' iron at intersection of N-S ¼ line and Sec. Line.
3) NW 45.75' – 5" W. Birch; 4) SW 37.98' – 8" Poplar; 5) South 47.85' – 8" Poplar; 6) North 29.04' – 1" pipe. Distance East – 2639.62'. Distance West 2666.59' to 'E13' [Really 'E1']
- **1995** – Unrecorded Survey – Ayres Assoc. – Job # 36-1057.00 – J. L. Jones (PS # 19838). Found ½" pipe.
7) North nail in 6" Elm 31.20'; 8) N50°E centerline mail box post 25.90'; 9) S60°E nail in Maple Clump 62.35'; 10) S20°E nail in 5" Birch 59.42'. Distance West 2666.94' – E13 [really 'E1']; Distance East 2639.26'
- **2015** – LCRC L. C300, p. 1317 – T. L. Lapham (PS # 27595) – No GLO corner or witnesses found. Found a ½" x 24" pipe (Point A) with the top 15" below grade with 1 witness that verified that it is the position set in 1980. This position was established from a rejected position for corner G13 therefore it was also rejected. The pipe used as witness in 1980 was considered as the corner but did not appear to be a reasonable position. So, corner F-13 was declared lost and now set at single proportionate measure to the GLO survey (Point B) between corners E-13 and G-13. This established F-13 position (Point B) was accepted as the best available evidence of the position of the corner. Point A may be a property controlling corner.
Set standard Midland County Remonumentation monument:
11) S04°E 11.69' fd. ½" pipe previously used for this corner. Point A above; 12) N43°W 36.23' set N & T in W. side of twin 10" birch; 13) N45°E 35.45' set N & T in 13" blue spruce; 14) S20°E 58.66' set N & T in 8" apple (measured at base of tree); 15) S05°E 43.55' center of 2" red pine; South 11'± centerline of road east-west

Page 2 of 2

Professional Surveyor's License No.: 26454