

SURVEY & REMONUMENTATION

APPROVED LAND CORNER
P.A. 345 OF 1990
MIDLAND COUNTY

OCT 03 1996

REMON. COR. C-9, GENEVA TWP.
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

256

For corners in
Midland

(County)

Located in:

Corner Code #

1. Public Land Survey

T 15N R 2W

C-9

T R

T R

T R

T R

2. Property Controlling
In Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN
MIDLAND COUNTY
REMONUMENTATION & FILED

22 AUG 96 8:04 A.M.

BEVERLY J THAYER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, RODNEY CLAYPOOL, in a field survey on MARCH 28, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-9 Corner common to Sections 19, 20, 29 and 30

Survey by Government, 1830's, set post

Survey by F. Gibbs, 1908, found post

Survey by R. Claypool, 1994, (Road Topo) found 1/2" rod and cap

LCRC by C. Roser, 1990, found 1/2" rod



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Corner common to Sections 19, 20, 29 and 30

Found 1/2" rod and cap per surveys by R. Claypool, and LCRC by C. Roser.

Corner C-9 was approved for remonumentation at a Peer Review Committee Meeting on 4/23/96.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Corner common to Sections 19, 20, 29 and 30

Found 1/2" rod and cap, replaced with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 in mon box per surveys by R. Claypool, and LCRC by C. Roser; and is accepted as the best available evidence of the position of the accepted corner.

S 75 Deg E, 42.76', nail in 10" Pine

N 60 Deg E, 47.43', nail in 10" Pine

N 40 Deg W, 113.29', railroad spike in 8" Cherry

N 80 Deg W, 84.69', nail in twin 6" Cherry

Signed by Rodney D. Claypool

Date 05-10-96

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983