REMON. COR. G-10, HOPE TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. B. A. 4070

	corners in	Filing Requi	rement of Act 74, N	vich. P.A	1970				
<u>Midl</u>	and (County)	Located in:	0	- ; }			50)8	
1. P	'ublic Land Survey	Located in: T <u>16N</u> R <u>1E</u>	Comer Code #			STATE	OF MICH	_	
		ŢR	G-10 RVEY &	-			AND COU	NTY	D
in	roperty Controlling Section	STREMONU	MENTATION	- ;		12/28/20	00 8:44	127 AM	1
3. M	liscellaneous roperty in Sec.	S T REB S T R	2 <u>3 2001</u>	-	Register of Deed		I. HAIN Re Numi		
4. Lo 5. Pi	ot No, Recorded rivate Claims	Plat SEC	CTION	L		<u> </u>	· · · · · · · · · · · · · · · · · · ·		
lines 1 in the c interior corner of the I	and 2 above were in conform current manual of survey inst r, Bureau of Land Managemen points mentioned in lines 3, 4 Michigan Board of Land Survey	rvey on May 30, 2000, do here flichigan P.A. of 1970, the corner ance with regulations and rules in ructions of the United States It tor by a decree of a Court of Lish and 5 above were in conform yors or by a Decree of a Court of cored, found as expressed below	r points mentioned on therefore as required Department of the aw and/or that the ance with the rules	9. 3.	2 - 6 - 3 4 - 7 - 5	D E F 5 4 1 8 7 9 17 7 16	3 - 10 - 15 -	11 14	1 12 13 13
NOTE	E: Not more than 2 come recorded on this certification	ers, all in the same town a	nd range, may be			1 1 - 1 - 21 - 21 - 21 - 21 - 21 - 21 -	22	23	24
				5	9 30 - 2	9 28 7	27-	26 -	25
A D.					12 - 31 - 3	2 - 33 -	- 34 -	- 35 -	36 -
		ent and accessories and/or s	ubsequent restorati	on:					
G-10	1/4 Corner common to Se	ctions 27 and 28							
B. Des	Survey by M. Hunter, 196 Survey by D. Whittier, 19 Survey by J. Schafer, 197 Survey by J. Jones, 1987 LCRC by J. Schafer, 197	?, old corner post standing i7, found 67, found 73, found ¾" pipe r, 1995, found 3, found ¾" pipe		the second property of		HODHEY CLAYPO LAME BANVEY No.	OR)		
G-10	1/2 Corner corner evidence	found and/or method applied	in restoring or rees	tablishing	corner:	20241	AND REAL PROPERTY.		
G.10	% Comer common to Sec Found %" pipe per survey	s by M. Hunter, D. Whittier,	J. Schafer, J. Jones	and LCR	C by J. Schafer		A STATE OF THE STA		
C Des	cription of management (*	and the second					
G-10	1/ Comment for co	rner and accessories establis	shed to perpetuate I	ocating th	e position of th	e corner:			
G-10	% Corner common to Sect Replaced pipe with 5/8" ro			a tigo					
	available evidence of the p	d and brass cap stamped Mi position of the accepted corn	diand Co. Remon C er.	or PS 292	241 in monume	nt box and	is acce	pted a	s the be
	N 5 Deg W, 22.30, nail and N 45 Deg E, 41.63, nail in S 45 Deg W, 62.0, centerli S 40 Deg W, 83.35, Northe S 35 Deg E, 63.38, mag na	power pole ne 24" Maple	:	Walking of the Control of the Contro					
igned b	Robins D.	Clayer		Det-	در . د ۱	_ 1			
urveyor	r's Michigan License No. 29		orm approved by Mich	⊔ate igan State	Board of Land S	urvevore la	n 28 10	74	
			•			Revised Ma Revised I.	y 14, 19	71	

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

13/37/58 JAG