

Land Corner Recordation Certificate
Attachment B to 2016 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is ONLY for corners filed under the 2016 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2016 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county

For corner(s) in: Midland County

Edenville Township

Corner Type	Survey Township				Corner Code
Original Public Land Survey Corner	T	16N	R	1W	B7
• MCL 54.202(g)	T		R		
• MCL 54.262(g)	T		R		
	T		R		
Property Controlling Corner	S		T		
• MCL 54.202(i)	S		T		
• MCL 54.262(h)	S		T		
	S		T		
Protracted Public Land Survey Corner	T		R		
• MCL 54.202(k)	T		R		
• MCL 54.262(i)	T		R		
	T		R		

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6			5		4		3		2		1	2
3														3
4		7			8		9		10		11		12	4
5														5
6		18			17		16		15		14		13	6
7														7
8		19			20		21		22		23		24	8
9														9
10		30			29		28		27		26		25	10
11														11
12		31			32		33		34		35		36	12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

- B7 – 1832 – GLO – H. Parke – Set ¼ post.
- 1) Elm 17" N46°W 12 L.
 - 2) Hickory 11" S35°E 21 L.
- 1852 – GLO Resurvey – A. Burt – Old government corner, set post.
- 3) Elm 12" S51°E 51 L.
 - 1) Elm 18" N46°W 12 L.
- 1898 – Minutes of Survey of Curtis Drain – Thence N. 21/100 chain to section line between Secs. 18 & 19 crossing Line 35/100 chains W. of ¼ Corner of said Sec. 18 and 19.
- 1901 – CSR L.1, p.92 – F.J. Gibbs – Old W. Oak post. No timber near for bearing trees.

Part B: Surveyor's Report on Perpetuation or Monumentation of Corner(s)

B7 – ¼ corner common to Sections 18 & 19, T16N, R1W – Dug 3' x 2 ½' area down 3'± deep into clay looking for evidence of wood post. No evidence of corner found. No evidence of GLO witnesses. Large drain culvert would probably have destroyed any evidence during construction. Based on retracement of Gibb's survey and occupation S, E & W. Set stamped 2½" brass cap on 5/8" x 34" rebar with 4" x 6" plastic tile with concrete around, down 0.8'. Measured N89°49'47"W 1320.00' (1320' – FJG) to Cor. '1', Sec. 19 – Fd. Sleigh Shoe; N89°49'47"W 2459.55' (2459.16' – GLO & FJG) to 'A7'; S89°45'39"E 2631.60' (2640' – GLO & FJG) to 'C7' and also East 1315.8' to Fences N & S. Corner also fits old fence occupation on N-S ¼ line south to 'B8'. Corner is 2'± N of centerline Gravel road to West, 8' W. of centerline Gravel road N & 26'± 2' E. of centerline Drain N-S. 2 ½" Brass Cap accepted as a careful and faithful perpetuation of position of the original corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner(s)

B7 – Stamped 2½" brass cap on 5/8" x 34" rebar with 4" x 6" plastic tile with concrete around-down 0.8' below grade.
S53°W 72.57' to set nail & tag in NW side of 45" R. Maple
S32°E 106.86' to set nail & tag in power pole
N82°E 111.45' to set nail & tag in N side of 19" Elm
N22°E 53.30' to set ½" x 18" rebar

Date of Observation	Latitude	Longitude	Datum and Adjustment Year	Epoch Date
June 11, 2015	N43°46'14.0414"	W84°28'38.0313"	NAD83 (2011)	2010.00

Position determined by direct GNSS static baselines from 2 Local OPUS Base stations. Adjusted by least squares.

I, Craig W. McVean, in a field survey on June 11, 2015, certify under the requirements of the State Survey and Remonumentation Act, 1990 PA 345, MCL 54.261 to 54.279, and the Corner Recordation Act, 1970 PA 74, MCL 54.201 to 54.210d, that the corner(s) identified and described hereon has been perpetuated or monumented as described in Parts A, B, and C above, pursuant to the laws and rules of the State of Michigan.

Craig W. McVean

Craig W. McVean

Professional Surveyor's License No.: 39088

Department of Natural Resources, 8015 Mackinaw Trail, Cadillac, MI 49601

12/7/2016

Date



I, Brian D. Ferguson, state that the corner(s) identified and described hereon and perpetuated or monumented as described in Parts A, B, and C above was presented to and reviewed by the Peer Review Group on August 3, 2016 and is accepted for filing in the Midland County Remonumentation Program.

Brian D. Ferguson

Brian D. Ferguson

Professional Surveyor's License No.: 26454

Date