

REMON CORNER A-10, EDENVILLE TWP.  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

538

For corners in

Midland

(County)

Located in:

Corner Code #

1. Public Land Survey

T 16N R 1W

A-10

T     R    

T     R    

T     R    

2. Property Controlling  
in Section

S     T     R    

S     T     R    

S     T     R    

S     T     R    

3. Miscellaneous  
Property in Sec.

**SURVEY &  
REMONUMENTATION**

**FEB 23 2001**

4. Lot No.       , Recorded Plat       

5. Private Claims       

**SECTION**

STATE OF MICHIGAN  
MIDLAND COUNTY  
REMONUMENTATION & FILED

12/28/2000 8:44:27 AM

SCOTT I. HAINES  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, **RODNEY CLAYPOOL**, in a field survey on **June 23, 1999**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-10 1/4 corner for Section 30 on West townline

Corner not set by Glo

Survey by F. Gibbs, 1908, set 35 links (23.1') North of Warren Twp. corner

Survey by MDOT, 1937, corner not found

Survey by M. Hunter, 1970, found 3/4" shaft

Survey by J. Jones, 1993, found

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-10 1/4 corner for Section 30 on West townline

Found 3/4" shaft at position per survey by M. Hunter and J. Jones.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10 1/4 corner for Section 30 on West townline

Replaced shaft with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 and is accepted as the best available evidence of the position of the accepted corner.

N 85 Deg E, 61.17', centerline R/W marker


S 80 Deg E, 64.08', nail in twin 24" Pine

N 70 Deg W, 51.13', nail in 24" Pine

N 35 Deg E, 110.97', spike in power pole

South 9.92', Warren Twp. corner M-10

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												



Signed by Rodney D. Claypool  
Surveyor's Michigan License No. 29241

Date 12-26-00

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983

APPROVED LAND CORNER  
P.A. 345 OF 1990  
MIDLAND COUNTY