

SURVEY &
REMONUMENTATION

APR 24 1995

COMMISSION

MONTCALM COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montcalm
(County)

Located In:

Corner Code #

1. Public Land Survey Sec. 34 T 11 R 5 H-13, S 1/4
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

STATE OF MICHIGAN
MONTCALM COUNTY
RECORDED

5 JUL 94 9:39 A.M.

VIRGINIA L. KNEPPER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, William Tingley a field survey on November 29, 1994,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1831, Robert Clark, Deputy Surveyor, GLO Notes

Set Post

Beech 8" N51°E 43 links

Beech 10" N36°W 13 links

October 19, 1877, F.A. Palmer, County Surveyor, Surveyor Notes

Made New Bearing Tree

Beech 14" N17-1/2°W 61'

February 20, 1990, W.G. Tingley #30104

Found 1" Iron Pipe

Railroad Spike East 114.8'

Southwest Corner House #9507 N45°E 133.9'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Iron Pipe.

Accepted as Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set remonumentation corner and monument box.

Nail and Tag Box Elder 16" N4°E 98.56'

Well Head N50°E 88.85'

4" Pipe S75°E 120.70

Southwest Corner House #9507 N45°E 133.9'

Section Corner Common to 3 - 4 T10N-R5W East 114.18'

This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

Signed by William Tingley Date 1/10/94
Surveyor's Michigan License No. 30104

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 27, 1971

REVISED MAY 1984

REVISED JAN., 1993

ADAPTED FOR WORD PROCESSING MARCH, 1993

ACCEPTED BY THE MONTCALM COUNTY SURVEY PEER
GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN
PUBLIC ACT 345 OF 1990 AT A MEETING HELD 1/26/94

William Tingley
William Tingley, PS, Chairman

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

LIBEL
PAGE 95