		:						
			LAND COR	NER RECORDATION	ON CERTIFICATE	· .		
				irement of Act 74				필요요
For	corners in						1777	
	Muskegon		Located In:	Corner Code	<i>≠</i> #		ొ ——	5 <u>0</u>
1.	Public Land Surve	y ·	T 11N R 17W				E2 C0	A STATE OF THE STA
	Property Controllin in Section Miscellaneous	\$. S .	T R T R T R T R	EMONUMEN APR 0 4 19		gister of Deeds S	tamp &	File Number
	Property in Sec.	8.	T R	COMMISS		<u></u>		
			led Plat			- ABCD	E F G	ніјк
5.		_	Nove		95	2 6 5		3 2
Stephen V. Vallier, P.S. I								
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land								
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a								-2223
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:								27-26-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded						11		
	on this certific					12 31 32	,}	34-35-
A. Description of original monument and accessories and/or subsequent restoration: Corner not set by GLO 1983 J. Lezarock found 1 1/2" Pinched Iron. Reset Monument Box over existing Iron. Recorded LCRC Liber 1277 Page 72.								
	SW 59 NW 49	1.67' 1.62' 1.09' 1.07'	10" Fruit Tree 18" Oak Power Pole Telephone Pole					
	(see Exhibit "A	\")						
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:							
	Found 4" x 30'	' Cast Iro	n Monument with Co	unty Survey Cap.	Checks witness	ses of LCRC Lib	er 1547	Page 679.
						OUTHER TUTIFIED OR COUNTY IN ACCORDANCE	CE :	
					WITH P.A. 34			
	•				Nev	. 13, 1995		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Found 4" x 30" Cast Iron Monument with County Survey Cap.								
	N 44 deg. E S 50 deg. E S 49 deg. W	42.99' 47.19' 42.07' 59.53' 96.03'		(set nail) Pole (found nail) Pak (found nail)	The state of the s	STEPHEN VALLIER Land Surveyor No. 28428	***	

Signed by .

Surveyor's Michigan License No. -

28428