UBER 1809 THE 327 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in Corner Code # Located in: Muskegon County SURVEY & REMONTATION G-7 T <u>11N</u> R<u>17W</u> 1. Public Land Survey R APR 2 8 1995 R Т COMMISSION R 2. Property Controlling S R Register of Deeds Stamp & File Number in Section 3. Miscellaneous Property in Sec. FGH Τ Κ CDE _,Recorded Plat 4. Lot No Private Claims_ 12 Donald G. Sandel ,in a field survey on Mar. 21, 1994 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points 13 18 mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the 24 21 United States Department of the Interior, Bureau of Land Management or by 19 20 a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of 28 25 30 29 Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 32 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (1) GLO: Set post corners sections 15, 16, 21, 22, July 2, 1837. Pine 10" N85°E 0.17 chains Maple 11" S73°W 0.20 chains (2) MCRC (1950's) no witnesses on record. (3) Found 5/8" rod, NE corner Section 21, from WS witness log, August 18, 1993; witnesses: N64°E 28.34' 12" W. Pine, S10°W 25.31' 16" Ash, N35°W 15.80' 12" W. Cherry, S20°E 37.67' 12" Maple, N84°E 38.43' 8" Maple. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (1) Found 1/2" rebar on W side of sand 2-track, ± extension of center line's Simonelli and Riley Thompson Roads; evidence of E-W fence line running to E. Verified corner location using existing witnesses. (2) Historical usage, documentation, and evidence of corner location reviewed and ratified by the Muskegon County Peer Group, February 1, 1994. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 4" D Cast Iron "County Survey" monument in place of found 1/2" bar; witnessed as follows: N35°W, found nail NE side, 12" Cherry, 15.84 POSITION OF SAID \$10°W, found nail W side, 17" Ash 25.31' \$60°E, set nail N side, 13" Maple, 42.12' RECORDED COTHER REVIEWED & RATIFIED S87°E, found West shore Capped iron, #30100, 32.94 BY MUSKEGON COUNTY N50°E, set nail SE corner, Power Pole, 42.59 PEER GROUP IN ACCORDANCE N02°E, set nail E side, 12" Ash, 36.95' WITH P.A. 345, OF 1990

Dunke 1994

Snald G. Sandil

Surveyor's Michigan License No.

25870:

CACTESSION STREET