LIBER 1809 FASE 339 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in **Muskegon County** Located in: Corner Code # 1. Public Land Survey T 11N R 17W 2. Property Controlling S <del>APR 2 8 1</del>995 in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. 4. Lot No\_ ,Recorded Plat FGH - 1 5. Private Claims ŧ۵ 11 12 Donald G. Sandel \_\_,in a field survey on Dec. 2, 1994 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and 18 16 15 13 rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by 19 20 21 23 22 24 a decree of a Court of Law and/or that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan Board of 30 29 28 27 26 25 Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: (1) GLO: Set quarter section post, December 31, 1836. Maple 12" N29°E 35 LKS R. oak 10" N37°W 55LKS (2) MCRC (1950's) no witnesses found on record. (3) Muskegon County witness Book Witnesses; 3/4" solid iron (CFL) S 2.2'± center line pavement, N55°E 89.88' 8" Pine, N40°W 42.75' 4" Twin Maple, S65°E 82.47' 6" Twin Maple, N10°W 35.62' 10" Pine. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (1) Found iron 2.4' N of center line River Road and Flush with surface; found a chisel (1/2" X 9.5") when digging through asphalt. At depth of 1.7', Hit Old Asphalt Road Bed and found 3/4" I.P. at surface; did not remove. Verified corner location using existing witnesses and by measuring south section line distances. (2) Historical usage, documentation, and evidence of corner location reviewed and ratified by the Muskegon County Peer Group, December 5, 1994. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 2 3/4" D Cast Iron "County Survey" monument in place of found iron/chisel; witnessed as follows: N40°E, set nail W side, 4" Maple in clump, 36,72' \$60°E, found nail SW side, Twin Maple 17", 82.50' \$25°E, set nail W side, N fence post (end), 52.23' POSITION OF SAID RECORDED CORNER N58°W, set nail SW side, Westerly gate post, 65.20' N36°W, found nail W side(almost covered), 12"Twin Maple, 42.74" REVIEWED & RATIFIED BY MUSICEGON COUNTY N15°W, set nail E side, Power Pole, 49.07' PEER GROUP IN ACCORDANCE

WITH P.A. 345, OF 1990

Surveyor's Michigan License No.

5870 × 126