3.3

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1999 DEC 22 AM 11: 24

## SECTION

## LAND CORNER RECORDATION CERTIFICATE

		Filing Requ	uirement of A	ct 74, Mich. P.	A. 1970	Ds.	
For corners inMARQUE	TTE	Located In:	Cor	ner Code #		RECIET	in a. Manley ER OF DEEDS OF
(County)				/		रस्य स्त्राच्या स	EN OF DEEDS DE
1. Public Land Sur	vev	T 45N R 25W		A-11 V		7	·
	,	T 45N R 26W		И-11 <u></u>			* * *
		TR T R					
2. Property Contro	olling S	TR					
in Section	" s	TR	_				700.0 40
3. Miscellaneous	S	TR T R				LIBER	m R2 page $ m 13$
Property in Sec	, s			<del></del>	Re	gister of Deeds 5	Stamp & File Numb
4. Lot No		d Plat		·			
5. Private Claims		<del></del>		,		BCDEF	<u>ені јк</u>
					2	654-	3 - 2
				40.00	3 -		
I, <u>GERALD W. CARLSON</u> , in a field survey on <u>May 27</u> , 19 <u>99</u> , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points						789	10-11-1
mentioned in lines 1	and 2 above v	vere in conformance v	with regulations	and rules therefor	reas <sub>5</sub>		4-1-1-1-
required in the current	manual of surv	ey instructions of the U	Inited States Dep	artment of the int that the comer n	erior, points 6 —	181716	15 14 1
Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:						<del>                                     </del>	<del>                                     </del>
						1'9 2'0 2'1-	22 -23 -2
					9 —		
NOTE: Not more than 2 corners, all in the same town and range, may be recorded					10	30-29-28-	27 26 2
on this cer	tificate,				11	31 32 33	34 35
A. Description of o	original monun	nent and accessories	and/or subsequ	uent restoration:	12	3,	
A-11: Corner comm T45N-R26W.	non to Section	ns 30 and 31, T45N-	R25W and Sec	tions 25 and 36	ra'	TIFIED BY PEEF	GROUP
1844: William A. Bu		ownship boundary su	ırvey notes des	cribe the corner	P.Ą	. 845 OF 1990	
monument as a woo	od post refere S44W 27	nced by: 'L 8" Y	. Birch N82	ΣE 3L	A	arry 4 ()	los
					DAT	TE	
1852: Martin M. Ha reference:	ıll's original su	bdivision survey note	es of T45N-R25	W, describe the	e corner monu	iment as a post a	no added a
12" Maple	SOE 5L	. 8" S	ugar N3	7W, 19L			
1852: Martin M. Ha	ill's original su	ibdivision survey note	es of T45N-R26	SW, describe the	e corner monu	iment as a post a	ind added a
reference:							
8" Sugar	N37W, 19	)L					
No Date: A survey son the perimeter of		. Brotherton, C.E. inc ake.	dicates a corner	402' North and	355' West o	of apparent mean	der corner location
1931 and 1952: A perimeter of Little S		by R.A.B. indicates	a corner 402' N	North and 355' \	West of appar	rent meander cort	ner locations on th
(SEE REVERSE SIDE	Ξ)			•			
A-11: 1999: No ori	ginal corner e	se found and/or meth vidence found. Found 2638.92', South is 3	d and accepted	storing or reesta a 1 3/4" square	ablishing come iron with a 2	er: ! 1/4" square top	projecting 1.5'
~		corner and accessor		to gernetuate lo	scating the no	sition of the com	ier:
A-11: 1999: Stamp Monument is 1.5' a	ed the accept bove ground.	ted monument with t Referenced by:	he appropriate	township, range	e, date, Profes	isional Surveyor r	number, and MCR.
4" Balsam 4" Twin Maple		.19' (SCA NBT-1980 .27' (SCA NBT-1980		Maple White Birch	S56E, N40W,	9.41' (GFA-NE 15.23' (GFA-NE	
Green Steel Sign Po	st w/ Yellow	Survey Marker Sign	S88E,	1.80'		ASS.	it of wichies
		face, butt, and side	nail blazes, d.h	. measuring nail:	s,	# d	GERALD W.
and stamped B.T. T T45N-R25W		ch Report 99100				#/ \	CARLSON SURVEYOR
						NE!	No.

Surveyor's Michigan License No.

<u> 24589</u>

## A-11:

## PART A CONTINUED:

.. 0 2000

1929-1931: A survey sketch by R.A. Brotherton, C.E. dated June 1929, indicates the corner as being established by Charles Cummings during June of 1931, 188' West of location of old comer iron. No description or references given.

No Date: Marquette County Road Commission notes from field book 643, indicate the corner is an iron pin with square head and description on it at a fence corner. No references given.

No Date: A survey plat by R.A. Brotherton, indicates a corner distance NOO-00-00E, 2641.3' to the East quarter corner of Section 25 T45N-R26W and distance S89-57-30W, 2630.0' to the South quarter corner of Section 25. No description or references of the monument were given.

1948: A survey plat of Big Shag Lake state public fishing site no. 52-1 by G.A. Shadko, indicates the comer is an iron pin with a 2" square on top 37' from a fence corner distance NOO-48-48E, 2639.4' to an iron pin stamped 1/4 cor. by Cummings. No references given.

1956: A survey sketch by Charles W. Ruhanen which is identical to the 1929/1931 R.A. Brotherton sketch, indicates the corner was established by Chas. Cummings during June of 1931. The comer position is shown to be 188' West of location of old corner iron position. No description or references given.

No Date: Department of Conservation coordinate list for Section 25, T45N R26W, indicates the corner is a I. Pin 2" sq. on top, 37' West from fence by Cummings. No references given.

No Date: A survey sketch by Gourdie Frasier and Associates, indicates the corner. No description of the monument or accessories.

No Date: A section breakdown and witness sheet by Gourdie Frasier and Associates, indicates the corner as a found 2" sq. iron stamped by Cummings with the following references:

Fence Post North. 1.02 White Birch N54W. 15.22 Maple S66E, 9.29 White Birch S21W, 16" 18.24

1979: An LCRC by Charles F. Clark, P.S.#25836, Liber 1 RC, Pg. 369, indicates that he found a 1 1/2" sq. iron with the following references: (with tags numbered R.L.S. 17618)

Fence Post North. 1.17 Maple \$70E 9.281 Я" Birch N40W, 15.20' PK nail in 3" Maple S65W, 6.281

1980: A Certificate of Survey by Sundberg, Carlson and Associates, Inc. (no Liber or page number), indicates the corner is a 1" sq. iron (18" high) with the following references:

Balsam N41E, 5.18' S64E, Maple 9.30 Maple S60W. 10" White Birch 6.291 N43W. 15.21'

1981: A Plat of Shag Lake Estates by Charles F. Clark, Liber 109 MR, Pg. 232-233, indicates the corner distance N88-55-06E, 2618.98' to the South 1/4 corner of Section 30, T45N-R25W. No description or references given.

1981: An LCRC by Gerry W. Carlson, P.S.#24589, Liber 4 RC, Pg. 170, indicates that he found a 1 ½" sq. iron at a fence corner North and East. Referenced by:

Balsam N41E, S64E, 5.18 Maple 9.30 10" 4" Maple S60W. 6.29 White Birch N43W. 15.21

1982: A section breakdown sketch by Sundberg; Carlson and Associates for the Minatorne Corp. survey, indicates the corner with a distance of N89-38-43E, 5186.06' to the Southeast corner of section 30.

1982: A Certificate of Survey by Sundberg, Carlson and Associates, Inc., Liber 1 SM, Pg. 436, indicates the corner as a 1" sq. iron (18" high) distance N89-23-01E, 2618.71' to a found steel fence post at the South 1/4 corner and distance NOO-19-36W, 2638.54' to a found 1 3/4" iron pipe with cap # 17618 at the West 1/4 corner of Section 30, T45N-R25W, with the following references:

Balsam N41E, 5.18 S64E, 9.301 Maple 10" Maple S60W. 6.29" White Birch N43W, 15.21

1983: A Certificate of Survey by Robert F. Cambensy, P.S. #19616, Liber 112 SM, Pg. 421, indicates the corner as a 1 1/2" sq. iron distance N89-54-36W, 1316.21' to a found 2" iron pipe with the following references:

Balsam N41E. 5.18' Maple S64E. 9.301 10" Maple S60W 6 29 White Birch N43W. 15.21

1984: A Certificate of Survey by Clark/Minard Surveys (no Liber or page number), indicates the corner distance N89-12-00W, 1316.10' to the East 1/16 corner and 5252.09' to the Southwest corner of Section 25, T45N-R26W. A reference is made to Liber 4 RC, Pg. 170 . No description or references are given.

1984: A Certificate of Survey by Charles F. Clark, Liber 1 SM, Pg. 519, indicates the corner distance N89-12-00W, 1316.10' to the East 1/16 corner. A reference is made to Liber 4 RC, Pg. 170. No description or references are given.

1985: A Certificate of Survey by Sundberg, Carlson and Associates, Inc., (no Liber or page number), indicates the comer as a 1" sq. iron (18"high) distance S88-31-05W,1316.14' to a found iron pipe at the East 1/16 corner and distance S88-31-05W, 2625.84' to a calculated position of the N 1/4 corner of Section 36, T45N-R26W, in Little Shag Lake used by Washburn, P.S.#6844,1964 and others. The following references are given:

Balsam N41E, 5.18 5 Maple S64E. 9.30 S60W, 10" Maple White Birch N43W. 15.21

1986: A Minutes of Survey prepared by David B. Babbitt, P.S.#21558 of the Michigan Department of Natural Resources-District 3-Region-1 office states: "On September 9, 1986 I received a request to survey the boundaries of State owned land in Section 30. A search of survey records disclosed monuments of record at the NE section corner, the SE section corner, the SW section corner and the Scuth 1/4 corner. These monuments were located and tied by a traverse along county roads. Said monuments seem to have been accepted by all previous surveys in the area and they appear to have been properly set. The South 1/4 corner seems to have been set by a reverse of the normal procedure on the original Gov't. Survey, i.e., the East 1/2 mile is recorded as 39.06 and the West ½ mile as 39.86. Our measurements are nearly proportional to that record. All of the above-mentioned monuments were accepted as found.

1989: A Certificate of Survey by Robert F. Cambensy, P.S.#19616 (no Liber or page number), indicates the corner as a 1 1/2" square iron distance \$89-54-36W, 1316.21' to a found 2" iron pipe at the East 1/16 corner and distance S89-54-36W, 2626.23' to a N 1/4 corner of Section 36, T45N-R26W, position in Little Shag Lake used by Washburn, P.S.#6844, 8-06-64. The following references are given: Nails in:

<sup>"</sup> 5.18 Balsam 'N41E, Maple S64E, 9.301 4" Maple White Birch N43W, S60W, 6.29 15.21

No Date: Survey notes of Bill Robey, P.S.#20711, copied by Gerry Carlson, P.S.#24589, indicate a found corner distance S00-06-05E,2631.511 to a found corner at the West quarter corner of section 31. No description or references given.