

JAN 10 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1999 DEC 22 AM 11:24

Patricia R. Manley
REGISTER OF DEEDS

For corners in

MARQUETTE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 45N R 25W

A-11/12 M.C. #6

T R

North shore

T 45N R 26W

M-11/12 M.C. #1

T R

North shore

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

LIBER R2 PAGE 191

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on June 21, 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-11/12: North Meander Corner common to Section 31, T45N-R25W and Section 36, T45N-R26W.

1844: William A. Burt's original township boundary survey notes describe the corner monument as a 12" White Pine referenced by:

12" White Birch N25E 11L

1953: A survey sketch by R.A. Brotherton, C.E., indicates a meander corner. No description or references given.

1987: An LCRC by Charles F. Clark, P.S.#25836, Liber 5 RC, Pg. 105, indicates a found drill rod with 2" square cap scribed: 31/36. The monument is 10' North of the shoreline and identical to the monument at the Northwest corner of the section.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11: 1999: No original corner evidence found. Found and accepted a 2 1/2" flat steel cap on a 1" drill rod flush with the ground. Distance North is 384.94', South is 1005.83'.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11: 1999: Stamped the 2 1/2" flat steel cap on a 1" drill rod monument with MCR 1999 on the top. Established the following references:

Southwest corner of sauna (concrete foundation)	N42W	20.58'
Southeast corner of sauna (concrete foundation)	N14W	20.05'
Southwest corner of concrete retaining wall	N62W	13.38'
Southeast corner of concrete retaining wall	N02W	10.76'
North shoreline	South	23.0'

T45N-R25W Corner Search Report 99100
BK. 12, Pg. 116

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

RATIFIED BY PEER GROUP

P.A. 245 OF 1990

DATE

10/25/99



Signed by

Gerald W. Carlson

Date

12-8-99

Surveyor's Michigan License No.

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995