MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced from one jack pine stump bearing N35°E 30 lks., a probably B.T. Corner lies 04 lks. east of a position midway and on line bet. two sec. cors.

SURVEYOR'S SEAL

CIRCLE CORNER REGISTERED

Signed Billy D. Buckler DATE 1/11/67

PEGISTERED LAND SURVEYOR