

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 NR. 29 W

M a r q u e t t e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 3, 4, 9, and 10,

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (S 9 NBT) S 83° W 18 Links

9" Cedar (S 10 NBT) S 14° E 23 1/2 Links

7" Cedar (S 3 NBT) N 32° E 22 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was replaced at Iron Rail set by unknown surveyor.  
Fould Cedar (doen) N 51° W 23 Links. No identifying marks. Found numerous  
old blazes at corner. Swp. edges N. and E. OK.

Corner was placed and witnessed September 29, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/13/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler