

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette Located In: Corner Code #
1. Public Land Survey T 46N R 30W E10
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 06/15/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E10) Quarter corner common to Sections 28 and 29. 1961 - Neal Sperhake RLS found and accepted an iron pipe described in the Ford Motor Company survey notes of 1923 as being the 1/4 corner. The pipe was found midway between Section corners 40.32 chains north and south and 27 links east of a straight line between them. Set 1"IDx36" I.pipe with aluminum Kimberly-Clark Corp. cap. Maple 4" S40°E 25.5 links, Maple 5" N70°W 26.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E10) Found the 1961 monument in good condition, substantially at the position described in the 1961 record, and accepted same as the best available evidence of the position of the original corner. The 1961 NBTs were not recovered.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E10) Found 1"ID I.pipe with alum. Kimberly-Clark Corporation cap. Set measuring nail with MDNR tag in the side of:
10" Y.Birch N78°E 9.15' mrkd "1/4S NBT"
6" twin Maple S53°W 26.0' do
10" Maple S27°E 16.8' overgrown blazes
10" Maple N49°W 17.05' do
Set sq'd cedar post adjacent.
E= 7917253.019 N= 175266.192

(F10) Found 1/2" rebar with plastic cap #44283 and #30097. Set measuring nail with tag in the side of the following trees:
10" Sugar S29°E 15.95' scribed blazes
10" Maple S41°W 20.7' do
9" Maple N15°W 3.75' do
12" Sugar N82°W 16.4' overgrown blazes
Set sq'd cedar post adjacent.
E= 7918048.830 N= 175258.776

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00
Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by [Signature]
Surveyor's Michigan License No. 33986

Date 08/11/2015

For the Michigan Department of Natural Resources, Forest Resources Division

