

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. <u>47</u> N. S., R. <u>25</u> E. W.	K-12, K-13
2. PROPERTY CONTROLL- ING IN SECTION_____	<u>35</u> , T. <u>47</u> N. S., R. <u>25</u> E. W.	<u>14</u>
3. MISCELLANEOUS PROPERTY IN SECTION_____	, T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

MARQUETTE  
CO.

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, David B. Babbitt do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on November 19 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_ 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- K-12 E  $\frac{1}{4}$  corner; Wood post Aspen 8 - N40°E - 08 lks; aspen 6 - S85°W - 04 lks. nothing found.
- K-13 S.E. Section corner; wood post aspen 8 - N10°E - 21 lks.; aspen 14 - N55°W - 12 lks. nothing found.
- 14 S. 1/16 corner on the east section line, not previously established.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- K-12 Set in centerline of N-S black top road in line with very old fence east - this position also causes the S. 1/16 corner on the east section line to fall in line with the centerline of blacktop roads west and north from that point.
- K-13 Set at corner of a very old fence north and east. This position fits the G.L.O. record to "top of hill" west - it also causes the S. 1/16 corner on the east section line to fall in line with the centerline of a blacktop road west and north from that point.
- 14 Set M.P.O.L. between the east  $\frac{1}{4}$  corner and the southeast section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- K-12 3/4" x 18" pipe; 4" sugar maple - N49°W - 25.50'; 5" sugar maple - S59°W - 28.25'
- K-13 1" pipe, 4" aluminum cap; 9" w. pine - N9°W - 31.40'; 9" r. maple - N45°E - 16.40'; D.N.R. - east - 9.24'
- 14 1" pipe, 4" aluminum cap; 6" w. pine - N19°W - 17.70'; 5" w. birch - S79°E - 12.00'; 3" w. birch - S89°W - 47.70'

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_  
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)