

SURVEY &
REMONUMENTATION

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD
1994 DEC 28 PM 5:54

JOB NUMBER: 94030
SHEET NO. : 1-429

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MARQUETTE

COMMISSION

Patricia A. Morley
REGISTER OF DEEDS

	(County)	Located In:		Corner Code #
		47N	25W	
1. Public Land Survey		T	R	B-1
		T	R	
		T	R	
		T	R	
2. Property Controlling	S	T	R	
in Section	S	T	R	
3. Miscellaneous	S	T	R	
Property in Sec.	S	T	R	

LIBER 1 PAGE 104
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

GERALD W. CARLSON

Tuesday, November 29

94

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-1: North 1/4 Corner Section 6. Not part of original survey. 1976: George B. Wilson, RLS No. 17607

Part A: 14" Sugar N53E, 38 1

7" Sugar NSW, 11 1

Top of Granite Nob 2.5 Chains West

Granite Nob 3 Chains East and 200 1 South

Part B: Found old humps and remnants of both above described bearing trees.

Also uncovered large area with shovel, and found

mark of old stake in sandy soil below, mark found had definite straight lines to sides, the remnants of the original BT's checked closely the called for distances and bearings given in "A" above. The reference to both Granite Nobs checked very close. Also found iron rod with plastic identification RLS 17618, 4.77'W, 1.2'S of corner above re-established. This has to be for the S 1/4 Sec. 31 as N 1/4 Sec. 6 was not established in the original survey. L1 R.C., Pg.142.

(See reverse side).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994 - Found and accepted iron as placed by G. Carlson in 1988.

Distance West is 2427.50' and distance East is 2629.71'.

RATIFIED BY PEER GROUP
P.A. 845 OF 1990

Larry J. Buasme
DATE Oct. 3, 1994

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1994 - Replaced 5/8" iron and cap #24589 with a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nails in:

10" Maple N88E 76.02 ft. Carlson NBT

18" Maple S84E 51.70 ft. Carlson NBT

4 1/2" Maple S71E 71.75 ft. Carlson NBT

18" Maple S49E 67.17 ft. Carlson NBT

Steel sign post East 1.0 ft.

Monument is 0.20' above ground and is on top of a berm.

Bk. 5, Pg. 57



igned by *Gerald W. Carlson*

24589

Date 12-22-94

urveyor's Michigan License No. _____

Record No. 429:

Part "A" Continued:

1988 - G. Carlson established the corner proportionately on line between the re-established NE corner of Section 6 and the found NW corner of Section 6. 26.34' West of the found S 1/4 corner of Section 31 and on line between the S 1/4 corner and the SW corner of Section 31. This corner was not recorded.

Referenced by:

8" Maple,	S89E,	76.25'
18" Maple,	S80E,	52.01'
4" Maple,	S78E,	72.02'
16" Maple,	S42E,	67.45'

9th
Geo
Geo