LAND CORNER RECORDATION CERTIFICATE JOB NUMBER: 93300 SHEET NO. : 1-355 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MARQUETTE (County) Corner Code ## Located In: T47N R 24W 1. Public Land Survey T47N R 25W __ R _R. _ R _ 2. Property Controlling in Section LIBER Miscellaneous Register of Deeds Stamp & File Number _ R _ _ T _ Property in Sec. ___ , Recorded Plat _ 5. Private Claims ___ in a field survey on Wednesday. December I, GERALD W. CARLSON do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 12 on this certificate. Description of original monument and accessories and/or subsequent restoration: A-10: Quarter Corner common to Section 30, T47N-R24W and 1976 - David Babbitt set a 1' pipe & 4" aluminum DNR cap Section 25, T47N-R25W. 1844: William A. Burt's original midway between the NW and SW corner of Section 30, survey notes describe the corner monument as a wood post Referenced by: 8" Sugar Maple N70E 11.00 ft. referenced by: 10" Sugar Maple S20E 27.15 ft. 24* Hemlock S52W, 27 1 14" Sugar N14E, 10 1 12* Sugar Maple N76W 10.60 ft. (See reverse side) L1 RC, Pg. 172 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1993 - The distance on the DNR map indicates the distance from the West 1/4 corner of the NW 1/4 corner of 19 is 2635.20 ft. The 1993 remonumentation survey measured this 1/2 mile distances 2624.08 ft. indicating a 10.12 ft. shortage from the DNR measurement in this 1/2 mile. The intent to monument this line by Dave Babbit was correct in the decision to proportion this line, and conclusive evidence to G.L.O. calls does not substantiate movement of his corners as monumented from the SW corner of Section 30 to the NW corner of Section 19, so accept corners as found. Peer group ratification 12-6-93. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1993 - Found Department of Natural Resources iron pipe and aluminum cap referenced by nails in: 16" Maple N68W 10.50 ft. Babbitt NBT 10" Maple N75E 11.43 ft. Babbitt NBT 20° Maple S25E 19.87 ft. 17" Maple \$31W 39.54 ft. Monument 1.0 ft. above ground. All distances above were measured to nails in trees with GcVN washers. Stamped MCR-1993 on cap of monument (Marquette County Remonumentation). Bk. 3, Pg. 154 GERALD W. CARLSON Signed by Sudd W. Carlson SURVEYOR __ Date . No. Surveyor's Michigan License No. _____24589

:

2015&BSURVEY

OFESSION

Record No. 355

Part "A" Continued:

1988 - Glenn Van Neste found a DNR monument referenced by:

13" MapleAz.288°10.50 ft.10" MapleAz.72°11.44 ft.18" MapleAz.153°19.94 ft.15" MapleAz211°39.57 ft.