## SURVEY & **REMONUMENTATION**

JOB NUMBER: 94030 SHEET NO. : 1-510

4. Lot No. 5. Private Claims \_

APR 2 8 1995

\_ , Recorded Plat

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1994 DEC 28 PM 5: 57

MARQUETTE COMMIS	SSION Located In:	Corner Code ≠≠
(County)	Localed III.	Comer Code
1. Public Land Survey	T 47N R 27W	M-2

Patricia R. Manley &

1.	Public Land Survey	T 47N R 27W	M-2	
		T R		
		T R		
		T R		·
2.	Property Controlling	S † R		A A PO
	in Section	S T R	<del></del>	LIBER $1$ PAGE $176$
3.	Miscellaneous	S † R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R	<u> </u>	

GERALD W. CARLSON , in a field survey on Tuesday, December 20 , 1994
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

	Α	В	<u>c</u>	D	E	<u>F</u>	G _	H	J	K	L	M
	Г		Γ	1		·						
2	一	6—	<u> </u>	5—	<del> </del>	4	一;	3 — 1	-	2—	1	
3	<u> </u>	╁	╀╌	<del> </del>	-		├	-	$\vdash$	-	H	
4	┡	<del>-</del>	╄	8	╄	! 9	ļ1	0	1	1	L-i	2
5	-	1	╄	ļ	┡			ļ	<u> </u>			
6	_	18	$\vdash$	  7	<del> </del> 1	  6	1	  5	1	4	-1	3
7	<u> </u>	<b>↓</b>	├	ļ	_	┞-	ļ		-	<u></u>		$\vdash$
8	ļ	 19—	<del>                                     </del>	20—		 ?1	-2	2—	2	3—		4
9	<u> </u>	↓_	╀	<u> </u>	<u> </u>	<u> </u>	ļ	<u> </u>	_	ļ	<u> </u>	
10	<u> </u> _:	] 30	<del>                                     </del>	! 29	<b>├</b> -2	! !8——	-2	7—	2	  6	<u> </u>	5
11	-	$\vdash$	├-	-	$\vdash$	-	$\vdash$	_	<u> </u>	_	H	
12	_	31—	<del> </del>	 32—	<del> </del>	 33	<del> </del>	  4	-3	  5—	<b>_</b> 3	6
13	L		上	1	<u> </u>	<u> </u>	<u> </u>		<u>L_</u>	<u> </u>		L

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

PK nail in utiltiy pole N70W 36.99' M-2: East 1/4 Corner of Section 1. 1844: William A. Burt's original survey notes describe the Hydrant valve nut corner monument as a post referenced by: SW corner building 9" Cedar N73E 13 l NW corner building 8" Fir N80W 6 1 Liber 4 RC, pg. 247 1983: A Land Corner Recordation Certificate filed by Charles F. Clark RLS No. 25836 indicates a 1 1/2" iron

1986: Certificate of Survey recorded Liber 357 pg. 568 filed by Larry Bussonne RLS No. 25833 indicates the East 1/4 Corner of Section 1, T47N-R27W as recorded in Liber 4, RC pg. 247. No corner accessories given.

N20W

N25E 80.491 N85E 27.81'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: Found and accepted the 1 1/2" iron pin as referenced in part "A" above. A 3/4" bolt was welded to the top of the pin and a Marquette County Survey Monument was place on top of the bolt. Distance South is 2618.45' (2618.79' Maas) and distance North is 2633.12' (2632.38' Maas). Corner is in centerline of Tobin St. South of Jackson St. in the City of Negaunee.

RATIFIED BY PEER GROUP

C.	Desci	ription	of monume	ent fo	or corne	r and	acce	ssories	esta	blished	to perpetuate	e locatin	g the	position	of the	comer:
															_	

1994 - Set a 3 1/4"diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner referenced by nail in:

Power Pole N74W 36.91 ft. Clark Accessory N25W 64.72 ft. Clark Accessory Hydrant (Northerly most valve nut) Southwest corner Senior Citizen Bldg. N27E 80.43 ft. Clark Accessory Northwest corner brick bldg. foundation N77E 27.80 ft. Clark Accessory

Monument is under a manhole cover and is set in concrete 0.95' below road surface. Bearing tree tags were

set on the power pole accessory but no sign post was placed.

Bk. 8. Pg. 57

Guald W Carlson Surveyor's Michigan License No. 24589

pin under manhole cover witnessed by:

GERALD W. **CARLSON** SURVEYOR No.