LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

-		
FOR	corners	117
1 01	COLLIELS	44.1

Marquette (County)	Located In:	Corner Code #											
1. Public Land Survey	T 48N R 29W T R R	J1 (GCDB 540700)											
2. Property Controlling in Section	S T R S T R	(GCDB 600700)											
3. Miscellaneous	s T R												
Property in Sec.	s r R												
			l R	enie	ter of	Паа	ade Si	tamn	2 Eil	a Mii	mho		
4. Lot No. Recorded Plat Register of Deeds Stamp & File Number													
5. Private Claims			1	B	C D	E	F	G	<u>H</u>	-	4	1	, M
			2	6—	 	, 4	j .	+	}	╄	<u>-</u>	<u> </u>	
Stenhan Szyszkoski in	ı, Stephan J. Szyszkoski , in a field survey on 06/08/15 do hereby state												
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2													
above were in conformance with regulations and rules therefore as required in the current manual of survey 5													
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7													
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8													
re-established, monumented, recovered, found as expressed below:													
,			9	┿	╆	-+	\dashv		+-	₩	╂	\vdash	-
NOTE: Not more than 2 corp	ers, all in the same town and range	manakatan 11.1	10	30	25	祌	2B	┿-	-27	╀╌	26—	2	5—
on this certificate.	ers, all in the same town and range	, may be recorded	11	╄	₩	-+	-	+	+-	╄	┼	\sqcup	\dashv
on this certificate,			12	<u> </u>	-32	<u>;</u>	<u>_3</u> 3.	+	_3 4	Ļ ₁) 5—	3	6
A Description of ani-to-to-			13	<u> </u>			丄		<u> </u>	<u>L</u>			J
	onument and accessories and/or s	subsequent restoration:											
(T1) Ossaskasa													

- (J1) Quarter corner common to Section 2 T48N-R29W and Section 35 T49N-R29W. 1846 Established by John Burt, Deputy Surveyor, midway and on the Township line between Section corners 40.00 chains east and west. The corner position is described in the original notes as "Quarter Section corner in lake" and was not monumented.
- (K1) Corner common to Sections 1-2 T48N-R29W and Sections 35-36 T49N-R29W. 1846 Established by John Burt, Deputy Surveyor, who set a Maple post witnessed by Y.Birch 30" N20°E 24 links, Hemlock 6" N80°W 22 links. 1988 Larry J. Bussone PS mentions the northeast corner of Section 2 in his recordations (L 5 of RC, Page 195) of corners I1 and K2, but does not mention monument type nor dimensions from those corners to K1. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J1) Reestablished the position for the corner midway and on the Township line between monumented Section corners 2646.95' east and west. The corner position falls in Wolf Lake and was not monumented. Established a Witness Corner on the Township line 1930.95' east of the corner position, on the east shore of Wolf Lake, 716.00' west of Section corner K1.
- (K1) The original post and accessories were not recovered. Found a 1.25" ID iron pipe, set firm, projecting 33" a.g., with an old Celotex location poster facing it and a blue paint line running N-S through it. Distances north to K11 and K12 T49N-R29W, both perpetuations of original corners, check very well with the GLO record. Distance east to 1846 call "47.00 Ledge one chain south of line" also checks very well. Distance south to K2 is short, which I have found to be not atypical of N-S lines in the east 1/2 of this township. This position was used in 1988 by L.Bussone to calculate the subdivision of Section 2 for a 1988 survey rec. in L368 P153. I accept the pipe as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap on the Township line 1930.95' east of the corner position for a WITNESS CORNER. Set measuring nail with MDNR tag in the side of: 15" Tamarack N13°W 57.3' mrkd "WC BT" 14" Tamarack N19°E 64.15' do 6" Maple N85°E 39.25' do	(K1) Found 1.25" ID iron pipe. Set measuring nail with MDNR tag in the side of: 8" Maple N49°W 12.2' mrkd "S35 NBT" 9" Maple S81°E 4.9' "S1 NBT" 4" Maple S07°E 14.8' "S1 NBT" 9" Spruce S41°W 11.75' "S2 NBT"
2" Spruce S51°E 35.95' do	9" Spruce S41°W 11.75' "S2 NBT"
Set sq'd cedar post adjacent. E= 7931834.287 N= 201546.653 (the Wit.Cor.)	E= 7932052.483 N= 201545.205

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83 (2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID AA8080: N= 192972.689 m. E= 7925456.741 m.

Signed by Liphur Royals Date 06/17/2015 * STEPHAN J.

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL STAT

LAND