## **SURVEY &**REMONUMENTATION

FEB 21 2001

## SECTION

MARQUETTE

1. Public Land Survey

For corners in

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

MARQUETTE COUNTY	
RECEIVED FOR RECOR	_

2000	DEC	22	AM	n:	15	
		ے دے	1371	IU.	-1/	۰

Patricia d. Manley REGISTER OF DEEDS On

. Property Controlling in Section . Miscellaneous Property in Sec.	T R S T R S T R S T R S T R	Register			PASE 28	
. Lot No, Ro	ecorded Plat	- 100				
		1 A B C	D E .	e G H	1 J K	+

I, GERALD W. CARLSON , in a field survey on October 19 TH , 2000 , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Located In:

T<u>48N</u> R 26W

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: C-1: Section Corner common to Sections 5 & 6, T48N-R26W

1846: Sam W. Hill's original subdivision survey notes describe the corner monument as a post 21 links West of the Corner Common to Sections 31 & 32, T49N-R26W referenced by:

Y. Birch 18" \$24E, 22 links Y. Birch 28" \$67W, 72 links

RATIFIED BY PEER GROUP
P.A. 345 OF 1990

April 11/4/60

DATE 11/4/60

1981: Robert E. Schmeling found a ½" dia. By 4' long iron pin and accepted it as the Section Corner Common to Sections 5 & 6, T48N-R26W and Sections 31 & 32, T49N-R26W, which is in error as the original GLO survey indicates double corners at the location. Mr. Schmeling verified this location by Original BT evidence he recovered, which witnessed the Corner Common to Sections 31 & 32. Mr. Schmeling did not recover the Yellow Birch witnesses listed above. Mr. Schmeling placed a 1" dia. By 4' long pipe with brass cap stamped to identify the corner over the found iron pin and established the following references:

 Hard Maple
 7"
 N66E, 14.9'
 (Scribed: S32 T49N R26W NBT)

 Hard Maple
 7"
 S56E, 11.9'
 (Scribed: S5 T48N R26W NBT)

 Hemlock
 7"
 S24W, 15.2'
 (Scribed: S6 T48N R26W NBT)

 Hard Maple
 8"
 N86W, 24.0'
 (Scribed: S31 T49N R26W NBT)

 5" Cedar Post/Tag
 North, 2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1: 2000: Found and accepted as the Corner Common to Sections 31 & 32, T49N-R26W the above described Schmeling monument. At the calculated position 13.75' West of the found monument a spike was placed and offset. The above listed GLO witnesses were measured: at Y. Birch, 18", S24E, 22 links - found 9" Hemlock with Y. Birch bark below it; at Y. Birch, 28", S67W, 72 links - found Y. Birch bark below surface. We then scraped away soil at spike and found a vertical piece of rotted wood 0.4' below surface and extending to a depth of 1.3'. This wood was badly decayed and had a slight curve at the bottom 3".

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1: 2000: At the spike location we set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.1' above ground and 89' +/- West of the centerline of Co. Rd. 510. Referenced by:

Balsam 14" N17E. 33.31 Maple 7" \$76E. 24.851 Schmeling NBT with DH nail 4" Maple S36W. 4.04 8" Maple N50E, 6.54

Southéast Corner Section 31, T49N-R26W N89°38'47"E, 13.75' Green Steel Sign Post w/ Yellow Survey Marker Sign N05E, 2.76'

Distance East 2648.54', distance West 2618.33'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Bk. MCR 15, Pg. 43 T48N-R26W Corner Search Sheet 2000035

Signed by Hurld W Carlso
Surveyor's Michigan License No. 24589

Date 12-(9-00

OF MICH

GERALD W.

CARLSON

24589

FORM APPROVED BY MICHIGAN STATE BOARD OF I