SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUEITE COUNTY
RECEIVED FOR RECORD

200 DEC 22 AM 10: 18

Patricia	A.	Man	.f	
Patricia REGISTER	0F	DEED	S Opin	

 ${f R}2$ page 288

For corners in	9	and the fact of the said that the said					
MARQUETTE (Gounty)	Located In:	Corner Code #					
1. Public Land Survey	T <u>48N</u> R <u>26W</u> TR TR	<u>G-1</u>					
2. Property Controlling in Section	STR STR						
3. Miscellaneous Property in Sec.	S T R S T R						
4. Lot No, Re 5. Private Claims	corded Plat						
hereby state that under requirementioned in lines 1 and 2 a required in the current manual interior, Bureau of Land Management	, in a field survey on No irements of P.A. 74. Michigan F bove were in conformance with real of survey instructions of the Lement or by a decree of a Court of above were in conformance with the survey in the conformance with the survey in t	P.A. of 1970, the corner points egulations and rules therefore as United States Department of the Law and/or that the corner points					

Register of Deeds Stamp & File Number

RATIFIED BY PEER GROUP P.A. 345 OF 1990

Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: G-1: Corner common to Sections 3 & 4.

1845: Sam U. Hill's original subdivision survey notes describe the corner monument as a wood post being 23 links East of the corner common to Sections 33 & 34, T49N-R26W, referenced by:

No subsequent records recovered

S41W.

44 links

18" Y. Birch

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-1: 2000: SCA survey crews conducted a thorough search of the area and found no evidence of monumentation except a nearby tree with a blue paint and East-West paint lines. The GLO line calls East and West checked reasonably well. Corner position was established at the GLO offset distance and on line between the SW and S 1/4 corners of Section 34, T49N-R26W,

C.	Description of monument for corne	and accessories estab	olished to perpetuate i	locating the position of the corner
----	-----------------------------------	-----------------------	-------------------------	-------------------------------------

G-1: 2000: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.2' above ground. Referenced by:

Hemlock

Hemlock

N63E, 7.49' 8.05' S17E,

8" Maple S60E, 20.89'

SW Corner Section 34, T49N-R26W S89°53'14"W, 15.19'

Maple

S50W, 13.741

Green Steel Sign Post w/ Yellow Survey Marker Sign S06W, 3.18'

Distance East 2637.71', distance West 2642.66'.

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed

Bk. 15, Pg. 79 T48N-R26W Corner Search Sheet 2000035 TE OF MICH GERALD W. CARLSON SURVEYOR No. 24589 OFESSION?

Huld Walsa higan License No. 24589 Surveyor's Michigan License No._____

22 links

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995