MARQUETTE COUNTY SICHIGAN

LAND CORNER RECORDATION CERTIFICATE PECTATO FOR RECORD Filing Requirement of Act 74, Mich. P.A. 1970 For corners in 1999 FEB 12 PH 3: 34 CHUNCH MARQUETTE Located in: Corner Code # REGISTER OF DEEDS ON (County) Ishpeming Township 1. Public Land Survey T48N R27W G-04 Т R т 2. Property Controlling Т in Section S Т 3. Miscellaneous Property in Sec. K2 mc 158 Register of Deeds Stamp & File Number 4. Lot No. _, Recorded Plat 5. Private Claims 1 2 3 I, <u>George M. Platz</u>, in a field survey on <u>December 7</u>, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in 4 lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 5 6 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: Я NOTE: Not more than 2 comers, all in the same town and range, may be recorded 9 on this certificate. 26 1/4 corner common to: T.48N., R.27W. Section 9 11 Section 10 T.48N., R.27W 12 RATIFIED BY PEER GROUP A. Description of original monument and accessories and/or subsequent restoration: P.A., 345 OF 1990 1848: Original US Government Survey by Wells Burt - Set wood post witnessed by:
N22°W 20 Links; 14* W Pine
S53°E 49 Links; 10* Spruce Pine Lang Il Sussa 198 DATE. 1980: L.C.R.C. recorded in L.1 of R.C., P.110, Marquette County Records. Gerald Carlson, PS 24589, iron equidistant on line witnessed by: set 5/8" capped 1.42'; 4" J Pine 12.71'; 4" J Pine 36.96'; 7" J Pine 7.53'; 8" J Pine S01°W S78°W N18°W N77°E 1991: Survey computation sheet for the breakdown of section 10 by Larry Bussone, PS 25833. No description or witnesses given. 1990 -1993: Various survey sketches and survey computation sheet for the breakdown of section 10 by Glen Van Neste, PS 27464. No description or witnesses given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" iron rod with cap no.24589. This corner was established for the breakdown of section 9 by Gerald Carlson, PS Found 5/8" iron rod with cap no.24589. This corner was established for the breakdown of section 9 by Gerald Carlson, PS 24589. A thorough search found no evidence of any other survey monumentation or occupation in the immediate area. The position of the corner has also been used in the breakdown section 10 per survey work by Glen Van Neste, PS 27464, and Larry Bussone, PS 25833. No evidence of original B.T.'s could be found. Line calls of the original GLO notes are not distinct enough to verify the position of this point. All measurements, obtainable recorded survey information and any other obtained unrecorded survey information made available to Spalding DeDecker Associates is documented in the research dossier. Considering the above information, all known evidence favors the correctness of this point.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced found 5/8" iron rod with cap no.24589 with standard Marquette County Remonumentation Monument, being a 2 3/8" diameter x 30" aluminum post with 3 1/4" diameter aluminum cap stamped with appropriate corner identification and "MCR 1998, PLATZ 38121". Made the following new witnesses:

Az. 50° Az. 82° Az. 175° Az. 194° North	9.44'; (7.19'; ; 13.52'; ; 1.35'; ; 0.90';	Set mag nail Set mag nail Set mag nail Set mag nail Found 2" O.D	with tag I with tag I with tag I with tag I . pipe	No. 38121 No. 38121 No. 38121 No. 38121	in NW. in S. in NW. in NW.	face of face of face of	9" 12" 6" 5"	Spruce with B.T. tag affixed. Spruce. Spruce stump.
Signed by	alou	M. Pl	17					Date Control of the c
Surveyor's Michiga	an License	No. 38121						