

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 50N R 28W	E5
	T R	
	T R	
2. Property Controlling in Section	S 16 T 50N R 28W	2
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 2 09/13/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E5) Corner common to Sections 8-9-16-17. 1992 - Corner monument recovered and recorded by Paul N. Bressette, PS 37270. Found 1" iron pipe and dead J.Pine witness N30E 48.2' set by MCRC in 1947. Replaced with MDNR monument. 12" J.Pine N10E 29.8', 8" Maple S10E 2.7', 4" Maple S89W 50.9', 6" Maple N14W 35.9'. Found no subsequent record.

(2-Sec. 16) East 1/16 corner between Sections 9 and 16. 1992 - Established by Paul N. Bressette PS 37270 midway and on line between Section and Quarter corners. Set MDNR monument. 10" Maple S64E 12.8', 10" Maple S70W 33.1', 10" Hemlock N88W 34.5', 10" Maple N03W 27.1'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E5) Found the 1992 monument in good condition and at record bearing and distance from two remaining 1992 NBTs. The Maple SE and the Maple NW are in good condition. The J.Pine NE and the Maple SW were not recovered. Accepted the monument as the best available evidence of the position of the original corner.

(2) Found the 1992 monument in good condition and at record bearing and distance from two remaining 1992 NBTs. The 10" Maple SW and the 10" Hemlock NW are in good condition. The other NBTs were not recovered. I did not make any measurements to this corner and this certificate is being filed to update the accessories of the monument as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E5) Ed. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 10" Maple S12E 2.7' scribing visible 6" Maple N86W 51.15' do 9" Oak N03E 50.7' mrkd "S9 NBT" 5" Maple S64E 4.75' "S16 NBT" Bearings are magnetic.

(2) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 10" Maple S67W 33.5' scribing visible 12" Hemlock West 34.8' overgrown blazes 6" Maple S70E 27.55' mrkd "1/16S BT" 12" Y. Birch N02W 38.7' do Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/08/2012

For the Michigan Department of Natural Resources, Forest Resources Division

