

JAN 11 1999

Approved by Menominee County	•
Land Survey Remonumentation	
Peer Group Under, Act 345 Of	
10 621	

	anth ceasis' were	
P.A. Of 1990 On _	10/26	_ 199 <i>. 25</i>
	I WALL	
	04-1	

the form	-	* 1 /	8 23 4
	6 13	- 64	100

expressed below:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	_		. Tala vi a
	MENOMINEE	Located In:	Corner Code :14	AUS SERVICE SE
1	Public Land Survey	T 33N R 27W	M-1	-8 -8
1.	1 Boile Land Carvey	T R		102 6 ₩ 2
		TR		5.信着
		, I n		
2.	Property Controlling	S T R		Z 🙃
	in Section	S T R		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Proporty in Sec	S T R		


5. Private Claims

(SAME ASM-13 T34N-R27W A-1 T33N-R26W) A-13 T34N-R26W)

William Lenca in a field survey on Oct. 24 19 95

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

, Recorded Plat



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1848: Original Survey by James H. Mullett B.T.'s Cedar, 8", SW, 13 lks. Tamarack, 10", NW, 31 lks. All original evidence has been destroyed by county road improvements.
 - 1981: L.C.R.C. No. 302 by William Lenca, RLS No. 26461, states that a 5/8" x 18" Iron Rod was set from information contained in a 1953 survey by Keith Roberts, Surveyor, on record with the Menominee County Road Commission. TIES: 8" W. Birch S38°W 46.91 feet; 9" Tam. S87°W 29.17 feet; Metal Sign Post N60°E 51.71 feet; Tel. Cable Box S18°E 92.22'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In our 1995 remonumentation survey, we recovered the 5/8" x 18" Iron Rod and 9" dia. Tamarack - S87°W - 29.17 feet. The White Birch B.T., Metal Road Sign and Telephone Cable Box have been removed or destroyed. The corner position falls at the PI of a North - South County Road centerline, and in line with the centerline of a County Road running East. This corner has been used by local surveyors for several years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

	•		
10" dia. Tamarack	N76 ⁰ E	103.13 fect	Scr. NBT
12" dia. Tamarack	S40°W	69.95 feet	Scr. NBT
10" dia, Tamarack	S87°W	29.17 fcct	Scr. NBT
9" dia. Cedar	N34°W	51.90 feet	Scr. NBT
Metal Survey Sign Post	West	27.35 feet	

ces are to nail in side of

WILHAM LENCA LAND SURVEYOR

REVISED JAN., 1983

NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of tree.

Signed by William Jon	Ud Date _	Oct. 24, 19	95
Surveyor's Michigan License No2	6461	FORM APPROVED BY I	NCHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISEO MAY 14, 1975