SURVEY & REMONUMENTATION APR 1 1995 LAND CORNER RECORDATION CERTIFICATE For corners in COMMISSION CONTROL MENOMINEE Corner Code ## (County) 33NR ___26W M.C. J/K-5 **Public Land Survey** ____ R _ R _ R **Property Controlling** in Section Τ. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat _ Private Claims 94 William Lenca Apr. 20 in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original Survey by James H. Mullett - B.T.'s - Tamarack, 4", N33°E, 08 lks & Tamarack, 3", S80°W, 18 lks. All original evidence for this corner has been destroyed by Highway construction. Michigan Highway Department Survey Plans show this corner as referenced to the centerline of Highway M-35 as being 1946: 68.65 feet East along the Section Line from station 593+34.45. L.C.R.C. No. 81, recorded by George B. Wilson, RLS No. 17607, states that he found a spike in the centerline of Highway 1974: M-35 at station 593+34.45 and set a 4" dia. concrete monument S89024'33"E, 68.65 feet. Certified Survey No. 32 by George B. Wilson, RLS No. 17607, shows this meander corner as it relates to the 1/4 corner to 1974 the West and to other lot corners in the survey. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 4 inch diameter round concrete monument from information contained in Certified Survey No. 32. This location matches with the location indicated in the 1946 Highway Department Survey. Our measured distance to the existing monument from the 1/4 corner is 881.25 feet. The GLO distance from the 1/4 corner between Sections 11 & 14, East to the Meander Corner was 17.45 chains (1151.7 feet), which would place the GLO Meander Corner in the Lake. The above mentioned concrete monument has been used as control for the East-West position of the Section Line between Sections 11 & 14, and is accepted as a REFERENCE MONUMENT to the Meander Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner in Miles Set 3-1/4" dia. Alum. cap stamped "REF. MON TO M.C." on existing 4" dia. Concrete Monument. WILLIAM LENCA N43°E Scr. NBT 9" dia. White Ash 57.08 feet SURVEYOR S490W 46.53 feet Scr. NBT 9" dia. White Ash N700W 154.79 feet Scr. NBT 8" dia. Cedar N210W 156.85 feet Scr. NBT 8" dia. White Ash S90°E 1.2 feet Survey Sign Post ERED LAND

NOTE: All bearings are magnetic bearings. All distances are measured with EDM tape. Distances to trees are to nail in side of tree.

Signed by Dilliam Fine	Date	Dec. 14, 1994
Surveyor's Michigan License No. 26461	- ,	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19

REVISED MAY 14, 1975