

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12/12 1996
Mr. David RLS
Chairman

For corners in

MENOMINEE
(County)

Located In:

Corner Code #

1. Public Land Survey

T33N R27W COS

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

96 DEC 20 AM 9:36
RECEIVED
REGISTER OF DEEDS
STAMP & FILE NUMBER

I, William Lenca, in a field survey on Jun. 27, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by John Mullett - B.T.'s - Cedar, 14" - S52°E - 08 lks; B. Ash, 9" - N43°W - 22 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1981: Certified Survey No. 223, recorded by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 8, T33N-R27W. No corner monument is described & no B.T.'s are given.
- 1981: Certified Survey No. 233, recorded by George B. Wilson, RLS No. 17607, shows this corner as it relates to other corners in Section 18, T33N-R27W. No corner monument is described & no B.T.'s are given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a railroad spike in the centerline of an East - West County Road and in line with an ancient fence running North. This corner position fits with distances North and East as shown in Certified Survey No. 223 and with distances South and West as shown in Certified Survey No. 233. This corner location fits with long standing occupation lines, has been used by local surveyors for several years and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

7" dia. White Ash	N10°E	37.38 feet	Scr. NBT
9" dia. Cedar	N52°E	58.91 feet	Scr. NBT
6" dia. White Ash	S15°E	61.55 feet	Scr. NBT
10" dia. White Ash	N55°W	72.32 feet	Scr. NBT
Metal Survey Sign Post	North	26.1 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Nov. 20, 1996

