Land Survey Remonumenta Peer Group Under Act 345 Of SURVEY & REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE 199 P.A. Of 1990 On Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MENOMINERPR 1 1 1995 Located In: Corner Code =## COMMISSION T 33N R 27W Public Land Survey 2. Property Controlling T in Section Miscellaneous .\_... R \_ Register of Deeds Stamp & File Number Property in Sec. \_ , Recorded Plat \_ Private Claims . 94 William Lenca Jun. 29 in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: Original Survey by John Mullett - B.T.'s - Alder, 3"- N600E- 05 lks; Alder, 3" - S310W - 06 lks. No original evidence for this corner was found. L.C.R.C. No. 113 by George B. Wilson, RLS No. 17607, states that this corner was set by single proportionate method. A 1975: 2" dia. Alum. Pipe 30" long, magnet top & bottom, stamped Land Survey Corner RLS 17607 was set. He shows the corner being located 227' West of a culvert and 64' South of the centerline of a gravel road. Certified Survey No. 49 by George B. Wilson shows this corner in relation to the NE and NW Corners of Section 32. It also 1974: shows the relationship of Wilson's measurement of this mile to that of A.L. Hillis' measurement in 1893. Description of corner evidence found and/or method applied in restoring or reestablishing corner: We found a 2" dia. Aluminum Pipe/3-1/4" diameter aluminum cap stamped "LAND SURVEY CORNER - RLS 17607". This corner was placed by single proportionate measurement and falls 64 feet south of the centerline of an East-West County Road. We accepted the monument as a careful and faithful re-establishment of the position of the original corner. MAPI NW LENCA LAND ERED LAND C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted 2" dia, Aluminum Pipe/3-1/4" dia. Aluminum cap stamped for corner: N050E 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 48.42 feet N840E 26.38 feet Scr NBT 10" dia. White Ash S07°E 48.12 feet Scr NBT 6" dia. White Ash S590W Scr NBT 23.20 feet 2" dia, White Ash S12°W 1.1 feet Survey Sign Post NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree. Nov. 18, 1994 Date . Surveyor's Michigan License No. . SHRVEYORS, JAN. 28, 1971 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND REVISED MAY 14, 1975 REVISED JAN, 1983

Approved by Menominee County