

SURVEY & REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/9, 19994

Mel Davis RLS
ACTING

RECEIVED FOR RECORD
94 DEC 12 AM 8:56
PAGE # 93 BK 1
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE 1143033

Register of Deeds Stamp & File Number

For corners in
MENOMINEE
(County)

COMMISSION

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 33N | R | 27W | E-3 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous Property in Sec. | S | | T | R | |
| | S | | T | R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William Lenca, in a field survey on June 28, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by John Mullett - B.T.'s - Cedar, 16", N61°W, 27 lks & Cedar, 18", N77°E, 05 lks. All original evidence for this corner location has been destroyed by county road improvements.
1980: Certified Survey No. 183 recorded by George B. Wilson, RLS No. 17607 - No description of the corner monument is given.
1981: Certified Survey No. 223 recorded by George B. Wilson, RLS No. 17607 - No description of the corner monument is given.
1981: L.C.R.C. No. 296, recorded by George B. Wilson, RLS No. 17607, shows this corner relative to other corner positions in Section 4 - No description of the corner monument is given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 5/8" diameter hex shaped iron 2 feet long was found 2 feet below the gravel road surface of an East - West County Road in a position which fits distances to corners as recorded in L.C.R.C. No. 296 and in Certified Surveys No. 183 and 223. The corner falls in line with fence lines running North and South from this location, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen A1NBF30 (Notched Base) Aluminum Monument stamped for corner location:

14" dia. Cedar	N47°E	59.72 feet	Scr. NBT
5" dia. Cedar	S30°E	52.43 feet	Scr. NBT
8" dia. Cedar	S45°W	34.45 feet	Scr. NBT
8" dia. White Ash	N37°W	87.08 feet	Scr. NBT
Survey Sign Post	South	25.3 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date July 09, 1994
Surveyor's Michigan License No. 26461