Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 199

	ORDATION CERTIFICA		P15
For corners in Filing Requirement of	of Act 74, Mich. P.A. 197	O Chairman	
MENOMINUE		·	
Located III. Corner Code	#	NAME OF L	,y
(County)			=
1. Public Land Survey T33N R 27W	I_3_	三型 5 2	
<u>TR</u>	<u>·</u>	155	5
TR		₩	75
2. Property Controlling STR	<u></u>	7 K	
in Section S TR		50° 4 7	\$ 60°
3. Miscellaneous S TR		· ~ (C	•
Property in Sec. S TR		Register of Deeds Stamp	& File Number
			
4. Lot No, Recorded Plat			
5. Private Claims		ABCDEFGH	IJKL
		2 5 5 4 3 - 3 -	_ _ .
		3	
I, William Lenca , in a field survey on Sep. 01, 1995	_ do hereby state that under	4 7 - 8 9 - 10	
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in	lines 1 and 2 above were in	5	
conformance with regulations and rules therefore as required in the current manua. United States Department of the Interior, Bureau of Land Management or by a dec		6 -19 - 17 - 1615	13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance w		7	
Board of Land Surveyors or by a Decree of a Court of Law, established, re recovered, found as expressed below:	⊢established, monumented,	8 19 20 21 22	23 24
NOTE: Not more than 2 comers, all in the same town and range, may be on this certificate.		10 30 -29 -28 -27	26 25
on and controller.			26 25
,		11 1 1 1 1 1	35 36
		12 31 32 33 34	35 36
A. Description of original monument and accessories and/or subseque		13	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
The Book part of angular monather and according and according to the second and			
1848: Original Survey by John H. Mullett - B.T.'s - Elm, 12",	S550W, 06 lks Hemlock 6	" N540W 251ks All origin	al evidence
has been destroyed by county road improvements.			
1902: Record of Survey by Albert Haas, County Surveyor, show	s partial subdivision of Sec	ction 12 and shows the location	on of corner
L-3 as it relates to other corners in Section 12. Haas' rec	ord states that a 4" Cedar F	ost was set from Government	B.T. (not
recovered) 1981: L.C.R.C.No. 301 by William Lenca, RLS No. 26461, state	en that a Dalland Culler -		
	es that a Kallroad Spike wa	as set " in line with centerline	s of county
roads East-West and South and in line with an old Fence line to the North. This position fits well with occupation lines to the East and West. TIES: Power Pole - North - 23.56' (found), Power Pole - \$30°E - 56.28' (found).			
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
In our 1905 Demonstration Summer Control of the state of			
In our 1995 Remonumentation Survey, we found that the railroad spike set in 1981 had been destroyed by county road improvements, however we recovered the ties and replaced the corner. The corner position falls in the centerline of County Roads			
running East - West and South and in line with an ancient fence running North. Measuring East from this corner, we found an			
ancient fence line at a distance of 1251 feet as compared to Haas' record distance of 1244.8 feet. Continuing East to the NE Corner			
of Section 12 in the centerline of a North-South County Road, we measured 2502 feet as compared to Haas' record distance of			
2,489.5 feet. It appears that the old fences in this area were constructed pursuant to Haas' 1902 survey. This corner location has			
been used by local surveyors for approximately 90 years, and is ac corner.	epted as the best available	evidence of the position of the	e original
WALLEY.	•		
	•	•	
C. Description of monument for corner and accessories established to p		on of the corner:	
Set 5/8" x 24" Iron Rod/3-1/4" Alum. cap stamped for corner local	ion in Monument Box:		
5/9th v 24th Team Dod/2th Alicen and modern through a same			
5/8" x 24" Iron Rod/2" Alum. cap marked "WITNE'SS MARK: 5/8" x 24" Iron Rod/2" Alum. cap marked "WITNESS MARK:	ER" N55 ⁰ E 38.08 fe	O 2	
5/8" x 24" Iron Rod/2" Alum, cap marked "WITNESS MARK	ER" S41°E 45.28 fe ER" S51°W 62.50 fe	9=1	
5" dia Ash	N20 ^o W 43.23 fe		
Survey Sign Post	S51°W 63.6 fee		•
NOTE: All borrings are married to the state of the state			-
NOTE: All bearings are magnetic bearings. All distances are milestrated with a steel tape. Distances to trees are to nail in side of tree.			
Nov. 24, 1995			
Signed by Children James * WILLIAM	Date	~·, 1///	<u> </u>
Surveyor's Michigan License No. 26461 \$ LAND	B		
S * : SURVEYO	:		
24461	PROVED BY MICHIGAN	STATE BOARD OF PROFESSIONAL SURV	EYORS, JAN. 28, 19