

FEB 11 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12/18 199 2
Mike Davis RLS
Chairman

For corners in
MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T34N R 27W

M-12

T R

T34 R26

A-12

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

97 DEC 22 AM 11:29
613 BK 5
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____
(SAME AS CORNER A-12 T34N-R26W)

I, William Lenca, in a field survey on Nov. 21, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	H
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey by H. Floyd - B.T.'s - Tamarack, 9" - S33°W - 40 lks.; Tamarack, 10" - N62°W - 43 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1981: Certified Survey No. 215 by William Lenca, RLS No. 26461, states in the legend that a 3/4" x 18" Iron Pipe with an identification cap was set.
- 1981: L.C.R.C. No. 292 by William Lenca states, "Set corner in centerline of County Road North and South and established midway between Section corners." - Set 3/4" x 18" Iron Pipe - TIES: Tamarack, 8" - N49°E - 48.08'; Tamarack, 8" - S49°E - 42.00'; W. Birch, 6" - N39°W - 48.70'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The iron pipe which was set at this location has been destroyed due to recent county road construction. We replaced the corner by using existing B.T.'s as indicated in Land Corner Recordation Certificate number 292 (see part "A"). The corner falls in the centerline of a North - South County Road and midway between the NE Corner and the SE Corner of Section 36, T34N-R27W. This corner has been used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod 3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

10" dia. Tamarack	N49°E	48.05 feet	Scr. NBT
9" dia. Tamarack	S64°E	54.48 feet	Scr. NBT
6" dia. Cedar	S28°W	77.94 feet	Scr. NBT
7" dia. Cedar	N44°W	49.48 feet	Scr. NBT
Metal Survey Sign Post	East	33.8 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 12, 1997

