

SURVEY & REMONUMENTATION

JUN 23 1994

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION
For corners in
MENOMINEE

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On 5/18 1994
Mc Davis
Chairman

RECEIVED FOR RECORD
94 MAY 20 PM 3:31
PAGE # 70 BK. 4
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE MI 49858

Register of Deeds Stamp & File Number

	Located In:	Corner Code ##
1. Public Land Survey	T <u>34N</u> R <u>27W</u>	<u>G-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, William Lenca, in a field survey on March 8, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Maple, 15", N59°W, 20 lks & W. Pine, 14", N14°E, 22 lks. All original evidence for this corner location has been destroyed by county road improvements.

1981: LCRC No. 298 recorded by George B. Wilson, RLS No. 17607, states that a 1/2" dia. iron rod was set by proportional measurement. B.T.'s - 5" Spruce, N30°E, 32.7' & 4" Cedar, S12°W, 42.2'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" diameter Iron Pin in centerline of East-West County Road. Also found Spruce and Cedar B.T.'s in proper location as noted by G. B. Wilson in LCRC No. 298. This Corner has been used for control in surveys in the area for at least 13 years and is accepted as a careful and faithful reestablishment of the position of the original corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Berntsen 2" Alum. Pipe 30" long with notched base 3-1/4" dia. cap stamped for corner:

12" dia. Balsam	Scr. NBT	N35°E	33.24 feet
5" dia. Cherry	" "	S41°E	90.81 feet
6" dia. Cedar	" "	S80°W	114.03 feet
8" dia. Cedar	" "	N70°W	103.40 feet
Survey Sign Post		North	33 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date April 22, 1994
Surveyor's Michigan License No. 26461