

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MEMORANDUM

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 35 N. S., R. 25 E. W.	I-4 & G-5
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 27, 1982, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- I-4 - E 1/4 corner of Section 10; 3" dia. pipe is also the S.W. corner post of a cemetery fence. This information based on a telephone conversation with Bill Lenca, R.L.S. Local residents agree.
- G-5 - S.W. Section corner of Section 10; 1/2" X 3' steel bar in center line of E-W road; B. Buckler R.L.S. - 7-17-56; 6" Soft Maple - S56°W - 47 1/2 lks; 8" Aspen - S53°E - 59 lks; set a wood post 15 links south of section corner scribed "S.C. 10' N."

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- I-4 - Bill Lenca - R.L.S. says the large pipe which is the S.W. corner post of a cemetery is also the east 1/4 corner of Section 10. Local residents agree. Witnessed the same as described in "C" of this form.
- G-5 - Found iron rod in center line of East-West dirt road 10' north of a sq. post scribed "S C 10'N". Set by B. Buckler - R.L.S. in 1956. Both of Bucklers NBT's are gone.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- G-5 - 1/2" by 3' iron bar; W. Ash 8" - N30°E - 34.3'; W. Ash 7" - N36°W - 22.3'; R. Maple 5" - S53°W - 39.2'; W. Ash 9" - S35°E - 24.3'.
- I-4 - 3" X 4 1/2' pipe southwest corner of cemetery fence; S.W. corner tombstone (John Wright) 4.5' - N27°E; S.W. corner tombstone (Andrew) N66°E - 15.5'; S.W. corner tombstone (LaBay) N81°E - 67.7'; N.E. corner of new house - N88°W - 93.2'.

SIGNED BY

David B. Babbitt

DATE

8-12-82

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)