SURVEY & REMONUMENTATION

JAN 09 2001

SECTION

Surveyor's Michigan License No.

Filing Requirement of Act 74, Mich. P.A. 1970 PA. 0f 1990 0n 7/13, 2000

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
· · · · · · · · · · · · · · · · · · ·

For corners in	• .	4	Chairman			
MENOMINEE	Located In: Corner Code #	Systematics and the state of th	Book	6	Page	. 147
(County)	35N 26W E-01		_			
1. Public Land Survey	T R E-01		Γ	RECE TUED	FOR RECORD	-
	ή <u> </u>			13 DEC 200		A
2. Property Controlling	TR STR				A MORRISON	
in Section	s tR		L	REGISTE MENOMINE	R OF DEEDS E. MI 49858	_
3. Miscellaneous	S TR					
Property in Sec.	5		Register	of Deeds	Stamp & File	Number
4. Lot No , Reco	rded Plat		h D C	DEF	G H I J	ז צ' ז
5. Private Claims	12 T3 (N D3 (N)			TT		
SAME AS CORNER E-I	i3 136N-R26W		2 6 3	- 5 4	3 - 7	21-
William Lenca	, in a field survey on $\frac{\text{May } 25}{\text{May } 25}$, 19 $\frac{00}{\text{May } 25}$ do hereby	state that under	4 7	- 8 9-	10-1	112-
requirements of P.A. 74. Michig	an P.A. of 1970, the corner points mentioned in lines 1 and 2	2 above were in	5	<u> </u>		
United States Department of the	d rules therefore as required in the current manual of survey in Interior, Bureau of Land Management or by a decree of a Cour	rt of Law and /or	6 18	_1716-	15-1	4———13-
that the corner points mentioned	d in lines 3, 4 and 5 above were in conformance with the rules y a Decree of a Court of Law; established, re-established	of the Michigan monumented.	7			
recovered, found as expressed by		, moramomou,	8 19	_2021_	222	3 24-
NOTE: Not more than 2 con	ners, all in the same town and range, may be recorded		9			
on this certificate.			10-30-	-2928-	272	625-
			11			
			12 31	_3233_	343	536-
			13			<u> </u>
•	onument and accessories and/or subsequent restoration		_			
evidence for this	by James H. Mullett - B.T.'s - Beech, 6" - N73°E - s corner has been destroyed by county road improve 7 No. 656 by William Lenca, RLS No. 26461shows J-R26W.	ments.				
	idence found and/or method applied in restoring or ree					
We found a Railroad Spi	ike in the centerline of County Road No. 358 (East-	- West) and in 1	ine with the	centerline	of a County F	Road
running North. This pos	sition matches measurements shown in Certified Su st available evidence of the position of the original	rvey No. 030, n corner.	us wen wim	existing in	ies or occupa	ши, ,
and is decopted as the co					OF SI	E WALLEY TO
				, K	TAIL .	" Apple
					willa Lenca	36 ★
				2005 42	LAND	
•				and the	SURVEY	S S
				Ŋ.	80601	
C. Description of monumen	t for corner and accessories established to perpetuate	locating the pos	sition of the co	orner: 🥞	EREN IN	AD SUPPLIED
Set 5/8" x 24" Iron Rod/	3-1/4" dia. Alum. cap stamped for corner location is	n Monument Be	ox:			
5/8" x 24" Iron Rod/j			6.39 feet		f Tcl. Box	
5/8" x 24" Iron Rod/j	plastic Ident. cap		54.96 feet		f Tel. Box	
4" dia. Cedar 5/8" v 24" Iron Rod/	2" dia. Alum, cap marked "WITNESS MARKER"		30.05 feet 52.00 feet	Scr. NB 1.0' E. c	f Power Pole	;
Metal Survey Sign Po			26.4 feet	2.0 25.	1101 1 010	,
NOTE: All bearings are	magnetic bearings. All distances are measured with	th steel tape. D	istances to ti	rees are to	nail in side o	f tree.

Aug. 8, 2000

Date