

SURVEY & REMONUMENTATION

JAN 09 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. Of 1990 On 7/13 2000
Wm Davis RLS
Chairman

For corners in **SECTION**

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 35N R 26W

G-13

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

SAME AS CORNER G-1, T34N-R26W

I, William Lenca, in a field survey on May, 19 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Cedar, 10" - N45°E - 18 lks.; Cedar, 18" - N40°W - 5 lks. All original evidence for this corner has been destroyed by County Road improvements.

1970: L.C.R.C. No. 765, Vol. 2 by Frank Bray states 2-1/2" iron pipe with 2'1/2" brass cap rewitnessed as set by the U.S. General Land Office in 1949. Monument is set at ground level in east wheel track of dirt road. TIES: 6" Cedar - S30°W - 24.9'; 13" Cedar - S46°E - 31.4'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 2-1/2 inch diameter iron pipe with 2-1/2 inch diameter brass cap in the East wheel track of a dirt road, and 2 Cedar B.T.'s as described in L.C.R.C. No. 765 (see part A). This corner has been accepted and used by local surveyors for 50 years, fits well with long standing lines of occupation to the North and West, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 2-1/2" dia. Iron Pipe/2-1/2" dia. Brass Cap stamped for corner location:

8" dia. Cedar	N27°E	27.26 feet	Scr. NBT
18" dia. Cedar (Existing)	S46°E	32.18 feet	Scr. NBT
9" dia. Cedar (Existing)	S30°W	25.11 feet	Scr. NBT
9" dia. Cedar	N51°W	57.7 feet	Scr. NBT
Metal Survey Sign Post	N75°E	13.6 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Aug. 8, 2000

Surveyor's Michigan License No. 26461

