

MAR 29 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1990 On 12/28 1999  
*McDermott RLS*

For corners in

MENOMINEE  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 35N R 28W I-07

T    R   

T    R   

T    R   

2. Property Controlling  
in Section

S    T    R   

S    T    R   

3. Miscellaneous  
Property in Sec.

S    T    R   

S    T    R   

BK. 6 Pg. 70

RECEIVED FOR RECORD

28 DEC 1999 3:56:09 PM

BARBARA MORRISON  
REGISTER OF DEEDS  
MENOMINEE, MI 49859

Register of Deeds Stamp & File Number

4. Lot No.       , Recorded Plat         
5. Private Claims       

I, William Lenca, in a field survey on June, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by Francis Coleman - B.T.'s - Cedar, 12" - N64°E - 21 lks.; W. Pine, 12" - S35°W - 32 lks. Remnants of stump for Original W. Pine B.T. still visible and used in 1960 to replace corner.
- 1960: L.C.R.C. No. 47 by Billy D. Buckler states corner was replaced from White Pine OBT S35°W 32 links. Stump cut high, B.T. in poor condition. Corner lies 50 links West of N-S Fence. B.T.'s: 16" W. Pine - S07°E - 47 lks; 13" W. Pine - S34°W - 72 lks; 9" Elm - N36°W - 20 lks. Set 1" Pipe with 4" Brass Cap.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1 inch diameter iron pipe with a 4 inch Brass Cap fitting 2 Pine B.T.'s as described in LCRC No. 47, Volume 2. Since this corner was replaced from an Original Bearing Tree, we accepted the existing monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 1 inch dia. Iron Pipe/4 inch dia. Brass Cap stamped for corner location:

12" dia. White Spruce	N80°E	33.27 feet	Scr. NBT
20" dia. White Pine (Ex. B.T.)	S07°E	31.35 feet	Scr. NBT
10" dia. Cedar	S76°W	51.21 feet	Scr. NBT
6" dia. Ironwood	N30°W	49.62 feet	Scr. NBT
Metal Survey Sign Post	West	1.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date July 2, 1999

