APR 0 6 1899

Approved by Menominee County Land Survey Remonumentation

Pa	r Group Under Act 345 Of
P.A. Of 1990	a 12/30 1998
	Ma spuis RLS
	Chairman
	Pites surve

SECTION

LAND CORNER RECORDATION CERTIFICATE

_ Filing Requirement of Act 74, Mich. P.A. 19	70
For corners in MENOMINEE Located In: Corner Code #	~ ~ ~ ~ ~
	705 RAI RER NEE
1. Public Land Survey T 35NR 27W A-11/12 T R T R 1. Public Land Survey T 35NR 27W A-11/12 T R T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	RECLIVED FOR RECORD RECLIVED FOR RECORD REGISTER OF DEEDS REgister of Deeds Stamp & File Numb
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G H I J K
(SAME AS CORNER M-11/12, T35N - R28W) # 3	2 6 5 4 2 2
William Lenca , in a field survey on Sept. 16 , 19 98 do hereby state that under	4 7 8 9 10 11
equirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
Inited States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or nat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 19 17 16 15 14 1
loard of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, ecovered, found as expressed below:	8 19 20 21 22 23
Not more than 2 corners, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 2
	11
	12 31 32 33 34 35 3
Description of original monument and accessories and/or subsequent restoration:	13
1847: Original Survey by H. Floyd - B.T.'s - Y. Pine, 24" - N55°W - 86 lks.; Spruce, 12	" - S75°W - 48 lks. All original evidence
for this corner has been destroyed by river crosion and ice jams. 1993: Plat of Survey by William Lenca shows he set a 5/8" x 24" Iron Rod/Ident, cap 25 along the West line of Section 31, T35N - R27W.	+/- from the Menominee River North
Description of corner evidence found and/or method applied in restoring or reestablishing corner. In our 1993 survey, we recovered a 3 foot long piece of railroad rail set vertically in the great 31, T35N-R27W. We found another piece of railroad rail sticking 6 feet above ground 519 line South 36.39 feet and set a 5/8 inch x 24 inch iron rod for a meander corner on the band distance from the NW Corner of Section 31 to the Meander Corner is 594 feet, compared to We therefore set our monument in place of the 5/8" x 24" iron and stamped it 36 T35N-R2 36.93 S.	ound at the Northwest Corner of Section 0.68 feet to the South. We projected this k of the Menominee River. The GLO o our measured distance of 556.07 feet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped 36 T35N-R28W/31 T35N-R27W REF. MON., M.C. 36.93 S.: STATE OF MISSING

6" dia. W. Ash	N300E	77.41 feet	"X" cut in upper and lower blaze
14" dia. Cedar	2830E	13.25 feet	"X" cut in upper and lower blaze
16" dia. Elm	N45°W	28.53 fect	"X" cut in upper and lower blaze
Railroad Rail	North	36.4 feet	
Metal Survey Sign Post	North	1.0 feet	

14 dia Codai	302-T	13.23 1000	A Cut in u	and towe	LUIAZES		Server has a to the	. A. A.
16" dia. Elm	N450W	28.53 fect	"X" cut in u	oper and lower	r blazes		WALLAM	2. 合
Railroad Rail	North	36.4 feet	•	•		#	Lenca Land	÷ 🕏
Metal Survey Sign Post	North	1.0 feet				3 +	SURVEYOR	\$
Menominee River	South	25 feet +/-				84	₩o. 24461 .•	: B
NOTE: All bearings are mag	netic bearings.	All distance	s are measured	with steel tape	Distances to trees a	ाट विक्रियों	in side of tree	6 V 1
Signed by William J	lenca_			Date	Dec. 22, 1998	Apply .	COULD SUPPLY OF THE SUPPLY OF	(SLEEP
Surveyor's Michigan License No	2646	I						_
	2010	•		-				