

5472

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Menominee
(County)

Located In:

Corner Code ~~##~~

- | | | |
|------------------------------------|---------------------------|------------------|
| 1. Public Land Survey | T <u>35N</u> R <u>29W</u> | <u>L-3, M-3.</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David Babbitt, in a field survey on 9/22/86, 19_____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-3. South 1/4 corner of Section 1.

M-3. SE section corner of Section 1.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-3. Found tubular metal fence post beside old square cedar post and channel iron fence post. This post has been used as the 1/4 corner by several registered land surveyors and is accepted as such by the local landowners.

M-3. Found 1/2" iron rod beside short steel fence post. East-west measurements indicate this to be too far east but I have no absolute proof of that. This iron rod has been used as the section corner on previous surveys by at least two other registered land surveyors.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-3. 1 1/4" tubular metal fence post.	M-3. 1/2" rod beside steel fence post.
4" W.Pine, N68W, 14.9'	4" Oak 17.5', N30W.
8" W.Pine, N5W, 18.2'	7" R.Maple, 31.6', N30E.
3" R.Maple, S74E, 8.7'	7" Oak, 28.00', S78E.
3" Oak, S15W, 10.3'	6" R.Maple, 29.25', S33W.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

David B. Babbitt

Date

1-27-87

Surveyor's Michigan License No.

RLS 21558