Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Service Survey

Line Survey Survey

LANC	CORNER RECORDATION CERTIFICATE	Chairman
Filing	Requirement of Act 74, Mich. P.A. 1970	वस्य प्र
For corners in Menominee Located in:	Corner Code ≠#	CEIVED JAN - J RB + J
1. Public Land Survey T	25M 311 1 25M K12	FOR BELLETS 3 MI ID 5 3 AVI ID 5 5 AVI ID 5 6 AVI ID 6 6 AVI
T T T	Re	gister of Deeds Stamp & File Number
5. Plysic Glaims		
1. Paul R Bressatte , in a field survey on a homopocepity that under requirements of P.A. 74. Mich.	chigan P.A. of 1970, the corner points mentioned	2 6 5 4 3 2 1 3 4 7 8 9 - 10 - 11 - 12 5 5 14 13 15 14 13
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:		7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.		12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:		13
Hamlock 6 H77E 11 lks. 1964: Billy D. Buckle Northwest and Southwest corners of Section 35 that it is. Recorded in Volume 3 p.413 Henomines (311) Quarter Corner common to Sections 26 and Aspen 8 S21M 30 lks. 1935: Billy D. Buckler witnessed by: 14° M. Ash 350E 28 lks.; 10° M (X12) Quarter corner common to Sections 35 and Hemlock 11 S48E 16 lks. B. Description of corner evidence found and/o (112) Found two of Buckler's witnesses as desc Pine, now dead, but standing with faces open a open and scribing visible. A new DNR monument a careful and faithful REESTABLISHMENT of the (J11) Found monument as described next to a wo 1955 survey (east 1955 - 2664.42', 1995 - 2663 accepted as a careful and faithful PERPETUATIO (K12) No evidence of original survey or restor Southeast corners of Section 35, and is accept Corner falls in a clearcut.	pitnessed by: 14: R. Pine RS4M 35 iks.; 14: County Records. 35. 1848: James H. Hullett, DS. Set wood p. RLS. Set 1" iron pipe with 4" brass cap fr. Ash HOJE 76 lks. Recorded in Volume 2, m. 36. 1848: James H. Hullett, DS. Set wood presented applied in restoring or reestablishing ribed, monument was missing. Mitness describing plain. Other two witnesses are in (1" iron pipe w/ 4"aluminum cap) was set from the properties of the original corner. Honument for deposition of the original corner. Honument for the position of the original corner. 86'; west 1955 - 2685.54', 1995 - 2684.41').	ost witnessed by: M. Pine 16 S04E 75 lks.; om original white pine bearing tree, umber 87 in Manominee County Records. ost witnessed by: Birch 14 S12M 25 lks.; g corner: ed as 14° R. Pine S40E was found to be a M. n excellent condition with blazes partly m M8T's and rewitnessed, and is accepted as alls in east wheel track of a woods road. It and west check well with distances from Monument was rewitnessed as found, and is
C. Description of monument for corner and acc	cessories established to perpetuate locating t	he position of the corner:
(I12) 1" iron pipe w/ 4" aluminum cap 13" R. Pine NB6E 28.4' old NBI 12" R. Pine S30E 39.3' (1/4S,NBT) 08" R. Pine S33N 50.15' (1/4S,NBT) 18" R. Pine H30N 23.1' old NBI All NBI's are blazed, scribed, painted and tagged. A metal post with sign was placed East 6 feet from monument. Distances are measured from notch in butt blaze, bearings are magnetic.	(J11) 1" iron pipe w/ 4" brass cap 05" Balsam M16E 37.3' (1/4S, MBT) 10" N. Ash N47E 17.7' (1/4S, MBT) 07" R. Maple S70E 28.5' (1/4S, MBT) 06" N. Ash S01M 41.85' (1/4S, MBT) All MBT's are blazed, scribed, painted and tagged. A metal post with sign was placed next to corner. Distances are measured to notch in butt blaze, bearings are magnetic.	(K12) 1" iron pipe w/ 4" aluminum cap 9" Spruce S82E 60.1' (1/4 S, M8T) 10" Spruce S18E 68.7' (1/4 S, M8T) 7" Balsam S5SM 11.85' (1/4 S, M8T) 11" Spruce M69M 45.95' (1/4 S, M8T) All trees are blazed, scribed, painted and tagged. A metal post with sign was set next to monument. Distances measured to notch in butt blaze, bearings are magnetic.
Signed by Yaul R. The	77770	
Surveyor's Michigan License No. 37270 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAM., 1983		