Land Surve	V Remonumeniation
Peer Group	Under Act 345 Of
0/ 1990 On	2/14 198

APR 0 6 1999

LAND CORNER RECORDATION Filling Requirement of Act 74,	ON CERTIF	FICATE	G.	uanuso
For corners in Filing Requirement of Act 74,	MICH. P.A.	. 1970	_ ಇಬ್ ಒ	
MENOMINEE Located In: Corner Code #			99 JAN PAGE # 7 BARBAI REGIS	RECEIVED FOR
1. Public Land Survey			75°9 RA MORE ITER OF DE INVEE, MI 4	
2. Property Controlling S T R		Regist	Second Stands of Deeds Stands	
4. Lot No, Recorded Plat	L	, togici	or or becas clair	ih a Lue Mallinel
5. Private Claims		1 A B	C D E F G	HIJKL
(SAME AS CORNER I-01, T36N - R27W)	,	2 6	5 4	3 2 1
William Lenca , in a field survey on Aug. 17 , 19 98 do hereby	state that und		89	10-11-12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and conformance with regulations and rules therefore as required in the current manual of survey in	2 above were i	in 5		
United States Department of the Interior, Bureau of Land Management or by a decree of a Cou	rt of Law and A	ا ا	17 16	15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules Board of Land Surveyors or by a Decree of a Court of Law, established, re-established	of the Michiga I, monumenter	ın d. 7		
recovered, found as expressed below:		. 8 19	2021	22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded		9		+ + + + +
on this certificate.		10—30—	2 ['] 92 ['] 8	27 26 25
		11		
•		12 31	3233 ;	343536-
A. Description of original monument and accessories and/or subsequent restoration	on:	13		1
 Original Survey by Francis Coleman (Sectional Subdivision) - B.T - 20 lks. All original evidence for this corner has been destroyed b L.C.R.C. No. 306 by William Lenca, RLS No. 26461, states "Set C to the S. This position checks well with GLO terrain calls N - S - Pipe - B.T.'s: PP - \$30°W - 43.08'; 14" Balsam - N61°W - 70.03'; 	y county roa for, in c/l of W and with	id improvemer E - W Co. Rd. an old fence 1.	in line with anci 2 mile E." Set 3	ient fence line
B. Description of corner evidence found and/or method applied in restoring or ree	stablishina c	orner:		
We found a 3/4" x 18" Iron Pipe in the centerline of an East - West County South. This position has been used for many years, fits existing lines of occ the position of the original corner.	Road and in	line with anci	ent fences to the s the best availab	North and le evidence of
			A STATE OF THE PARTY OF THE PAR	W Michael
		•	July 2 1 1 1 1 E	
				Veliam & E Lenca & Land Land Lanveyor 2006
C. Description of monument for corner and accessories established to perpetuate le	ocating the p	osition of the c	orner:	STORY THE
Set 2" dia. Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corne	er location:	-	CO. CO.	accommission of
5/8" x 24" Iron Rod/Identification Cap 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 7" dia. Cedar Metal Survey Sign Post	North S29 ^o E S69 ^o W N51 ^o W North	33.00 feet 70.57 feet 96.13 feet 77.54 feet 33.5 feet	1' W of 5" Popla 1' S. of Tel. Box Scr. NBT	
NOTE: All bearings are magnetic bearings. All distances are measured with	h steel tape.	Distances to	trees are to nail i	n side of tree.
Signed by 10) Chambana _	Dete	Oct. 05, 1998		
Surveyor's Michigan License No.	Date		<u></u>	
Curveyor's Michigan License No. 26461				