

P.A. Of 1990 On 12/20 19995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
MENOMINEE  
(County)

Located In:

Corner Code #/1

- |                                       |   |     |   |     |     |
|---------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey                 | T | 36N | R | 28W | K-3 |
|                                       | T |     | R |     |     |
|                                       | T |     | R |     |     |
|                                       | T |     | R |     |     |
| 2. Property Controlling in Section    | S |     | T | R   |     |
|                                       | S |     | T | R   |     |
| 3. Miscellaneous Property in Sec.     | S |     | T | R   |     |
|                                       | S |     | T | R   |     |
| 4. Lot No. _____, Recorded Plat _____ |   |     |   |     |     |
| 5. Private Claims _____               |   |     |   |     |     |

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, William Lenca, in a field survey on Oct. 30, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by Francis Coleman - B.T.'s - Hemlock, 20" - N65°E - 48 lks; W. Pine, 18" - S23°W - 22 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1976: L.C.R.C. No. 132 by David Babbitt, RLS No. 21558, states that he found a 3/4" iron rod in centerline of roads N-E & W, and in line with old fence south. He set a 1" dia. iron pipe/4" aluminum cap in place of the 3/4" iron rod and took the following ties: 6" dia. Red Pine - S06°W - 54.0' (Gone); 4" Thorn Apple - N26°E - 39.2' (good condition); Plastic RLS cap in Power Pole - N72°E - 77.4' (found).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In a 1995 survey and section subdivision of Section 11, T36N-R28W, we recovered a 1 inch diameter iron pipe with 4 inch diameter aluminum cap in the centerline of County Roads East - West and North, and in line with an ancient fence to the south. We also recovered 3 of the corner ties as indicated in part "A" above. This corner position has been accepted and used by local surveyors for more than 20 years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 1 inch diameter iron pipe/4" dia. aluminum cap stamped for corner location:

Plastic RLS cap in Power Pole (recorded as 77.4')	N72°E	77.38 feet	Scr. NBT
5" dia. Thorn Apple (recorded as 39.2')	N26°E	39.20 feet	
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N11°E	77.12 feet	
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N60°W	46.34 feet	
Metal Survey Sign Post	N60°W	47.7 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with a steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date Nov. 04, 1995

Surveyor's Michigan License No. 26461

