

SURVEY & REMONUMENTATION

MAY 28 1997

COMMISSION

For corners in

MENOMINEE
(County)

Located in:

Corner Code #

1. Public Land Survey

T37N R. 25W

A08

2. Property Controlling in Section

S

T

R

3. Miscellaneous Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

SAME AS CORNER M-8 T37N-R26W

I, William Lenca, in a field survey on Jun. 19, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey (Twp Bdy) by James H. Mullett - B.T.'s - Tamarack, 12" - S47°W - 16 lks.; Tamarack, 12" - N30°W - 23 lks. Original evidence destroyed by county road improvements.
- 1986: L.C.R.C. No. 743 recorded by William Lenca, RLS No. 26461, states that a Railroad Spike was set proportionately between the NW Cor. of Section 18 & SW Corner of Section 19. Ties: 6" Ced. - N54°E - 54.18'; 9" Tam. - S35°E - 57.97'; 8" Ced. - S41°W - 54.71'; 6" Tam. - N46°W - 46.84'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a railroad spike and 4 Bearing Trees marked NBT as described in L.C.R.C. No. 743. (See part "A") The railroad spike was found 5 feet North of the centerline of an East - West County Road (C.R. 374) and at a proportional location between the NW Corner (A-7) and the Southwest Corner (A-9) of Section 19, and is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

6" dia. Cedar - Ex. B.T.	N54°E	54.18 feet	Scr. NBT
9" dia. Tamarack - Ex. B.T.	S35°E	57.97 feet	Scr. NBT
8" dia. Cedar - Ex. B.T.	S41°W	54.71 feet	Scr. NBT
6" dia. Tamarack- Ex. B.T.	N46°W	46.84 feet	Scr. NBT
Metal Survey Sign post	South	33.0 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by

William Lenca

26461

Surveyor's Michigan License No. _____

Date

Sep. 24, 1996

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 9/25 199 96

Mike Davis RLS
Chairman

RECEIVED FOR RECORD
96 OCT -7 PM 3:27
PAGE # 364 BK. 4
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE COUNTY

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

