

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1990 On 12/27 1996  
Mel Davis RLS  
Chairman

For corners in

MENOMINEE  
(County)

Located In:

Corner Code #

1. Public Land Survey

T<sub>37N</sub> R<sub>25W</sub> G02

T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

2. Property Controlling  
in Section

S<sub>1</sub> T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

S<sub>1</sub> T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

3. Miscellaneous  
Property in Sec.

S<sub>1</sub> T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

S<sub>1</sub> T<sub>37N</sub> R<sub>25W</sub> \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Oct 11, 1996, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1852: Original Survey by George Adair - B.T.'s - Cedar, 12" - S56°W - 16 lks.; Cedar, 12" - N55°W - 20 lks. All original evidence for this corner has been destroyed by logging activities.
- 1983: PLAT OF SURVEY by Mel Davis, RLS No. 16926 states: Found remains of wood post and witness stake - set 1-1/2" x 40" iron pipe." B.T.'s (from field notes) - Tam., 6" - S48°W - 23.37'; Tam., 8" - N67°E - 35.0'; Ced., 7" - S50°E - 20.42'; Twin Cedar, 12" - N41°W - 17.56'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 1 inch diameter iron pipe and 4 B.T.'s as shown in part "A" above. This corner has been accepted and used by local surveyors for many years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum. cap stamped for corner location:

9" dia. Cedar	N45°E	18.63 feet	Scr. NBT
6" dia. Tamarack (Ex. B.T.)	S48°W	23.37 feet	Scr. NBT
7" dia. Cedar (Ex. B.T.)	S50°E	20.42 feet	Scr. NBT
12" dia. Twin Cedar (Ex. B.T.)	N41°W	17.56 feet	Scr. NBT
Metal Survey Sign Post	N65°E	1.80 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Dec. 26, 1996

