Approved by Menominee County
Land Survey Remonsmentation
Peer Group Under Act 345 Of
PA. Of 1990 On 72/27 199 62

	Filing	Requirement	of Act 74, Mich. P.	.A. 1970		Chairm	RAUN P	, <u>L</u>
For corners in						(6.5	10	
MENOMINEE (County)	Located in:	Corner Code	#	•			MARKET 3	,
1. Public Land Survey	77N R 24	w	G03.					;
	TR_					<u> </u>	80 7	1
•	<u>TR_</u>					<i>∞</i>		2
2. Dranarty Controlling		-				엄청등지	co :	•
Property Controlling in Section	S TR_ S TR_	-				ું કુ.∀ે	07	•
3. Miscellaneous	S T R					•	7	
Property in Sec.	s rR				Register o	f Deeds Sta	amp & Fil	e Number
4. Lot No, Recorde 5. Private Claims	ed Plat	 		1	BCI	EFG	H I	JKL
5.7 1175to Oldino				2		<u>.</u>	_{	. <u>!</u>
		•		3			_ _ _	+++
i, _William Lenca	in a field survey on	Δυσ 27 19 9	6 do hereby state that	under 4	,	3	10	-1112-
requirements of P.A. 74, Michigan	P.A. of 1970, the corner :	points mentioned in	ı lines 1 and 2 above w	rere in				
conformance with regulations and ru United States Department of the Info				or trie		7 1-16		
United States Department of the Ind that the corner points mentioned in					,	,		1 1
Board of Land Surveyors or by a	Decree of a Court of i			ented, '				
recovered, found as expressed below	NT.			8	192	V———21——	-22	.23 29~
NOTE: Not more than 2 come	s, all in the same town a	and range, may b	e recorded	9			-1-1-	1-1-1-
on this certificate.				10	302	928	-27	-2625-
				11				+
				12	313	233	—3 '4—	.3536
				13				
 Description of original mont 	iment and accessories	and/or subsequ	ent restoration:					
original evidence	by George Adair - B.7 for this corner has been by Mel Davis, RLS 3 (decayed) - set 1-1/2* - 41.47.	en destroyed by No. 16926 states	logging activities. s: Found squared w	ood post ar	ıd possible	remains of	original	
				ng oornos:				
B. Description of corner evide								
We recovered a 1 inch diar remnants of a large hemior double proportional position evidence of the position of	k stump to badly deca n between corners G-	eved to determin	ie if it was an origin	al. The ex	isting iron	pipe fits ve	ery closely	y with a
		•					- norman	יי יינונת
						TITUL	LE OF E	CALCAR
							WILLE	M . 76 E
						# :	LENC	
			tueta legating	tha nacition	of the corr	.er +	LANI SURVEY	
C. Description of monument fo Set 2" dia. Aluminum Pipe	r corner and accessor /3-1/4" dia. Alum. ca	es established to p stamped for co	orner location:	tite position	Of BIS COL		No. 2646	
7# die Deleare	N31 ⁰ E	24.38 feet	Scr. NBT			· All	750	CUR'I LITTLE
7" dia. Balsam 10" dia. Cedar (Existing	_	24.38 feet 33.18 feet	Scr. NBT			ΨŽ.	MI O IN	ELTO -
10" dia. Cedar (Existing		13.35 feet	Scr. NBT					-
9" dia. Cedar (Existing I		41.47 feet	Scr. NBT					
Metal Survey Sign Post	N380W	1.00 foot						
NOTE: All bearings are m	agnetic bearings. Al	l distances are n	neasured with steel t	tape. Dista	nces to tree	es are to na	il in side	of tree.
1				D 1	ic 1004			
Signed by (1) Main	n Fuer.		Date .	Dec. 2	26, 1996			
Surveyer's Michigan License No	26461	***						
out refer a microgan chembe in								