ſΈ	1	pproved b and Surve Peer Grou 90 On	y Remoni	mentations to the second secon	n f 99 <u>/</u>
)		1141	mu	Re	ک
			Chairman		
,		競技	95 DEC 30 // 9: 06	TO DEPOSIT OF THE SERVICES	
Regis	ster of D	eeds St	amp &	File Nu	mber
1 B B 1 2 3 4 5 5 6 7 7 8 19 9 10 30 - 30 - 11 12 31 - 13	20-	9		-1114	12- 12- 13- 24- 25- 36-
r. d notes - 61.64	in my of feet (Go iron @ !	fice ind	icate th	at we	-

LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Gazirnan 1
MENOMINEE Located In: Corner Code #	- 55 S
(County)	S DEC 30
1. Public Land Survey 57N R 25W 104	
<u>TR</u>	
<u></u>	71.75
2 Bronoth Controlling S T B	
2. Property Controlling S T R in Section S T R	
3. Miscellaneous STR	2 1 o
Property in Sec. S T R	Register of Deeds Stamp & File Number
	Register of Decide Stating at 11th Homes
4. Lot No, Recorded Plat	— ABCDEFGHIJKLA
5. Private Claims	- 1
	2 - 6 - 5 - 1 - 3 2 1 -
William Lenca Nov. 06 96	3
I,, in a field survey on, 19 do hereby s	
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 conformance with regulations and rules therefore as required in the current manual of survey inst	
United States Department of the interior, Bureau of Land Management or by a decree of a Court	
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of	
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	9
on this certificate.	10 30 29 28 27 26 25
	11
	12 - 31 - 32 - 33 - 34 - 35 - 36 - 36 - 36 - 36 - 36 - 36 - 36
corner evidence was destroyed by county road improvements.	, w
B. Description of corner evidence found and/or method applied in restoring or rees	tablishina corner
We recovered a P.K. Nail set in the centerline of county roads North - South found this P.K. nail in a 1988 survey and took the following ties to it: Power bottom step of Church - N55°E - 68.32 feet (found); Power Pole - S05°E - 153.30 feet (found). This corner has been accepted and used by local surveyor evidence of the position of the original corner.	Pole - N47°W - 61.64 feet (Gone); NW Cerner of 13.37 feet (found); 1/2* iron @ base of sign - S50°W -
C. Description of monument for corner and accessories established to perpetuate leads to 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in	ocating the position of the corner
NW Corner of Church Bldg	N550E 82.89 feet
NW Corner of Residence foundation	S28 ^o E 142.19 feet
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	\$45°W 53.53 feet 0.5' NW of Rd Sign
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N43°W 45.37 feet 0.5' SE conc. marker
Metal Survey Sign Post	N43 ⁰ W 46.8 feet
NOTE: All bearings are magnetic bearings. All distances are measured wit	h steel tape. Distances to trees are to nail in side of tree.
1 M	Dec. 26, 1996
Signed by 11 1 Man Tenra	Date
Surveyor's Michigan License No. 26461	
JULY 46 YOL S TATION GATE LICENSO TAO.	