

SURVEY & REMONUMENTATION

APR 24 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of

P.A. Of 1990 On DEC 16 199 4

Mel Davis RLS  
Chairman

RECEIVED FOR RECORD  
94 DEC 27 AM 10:46  
BAGG #169 BK-4  
BARBARA MCCRISON  
REGISTER OF DEEDS  
MENOMINEE MI 49853

Register of Deeds Stamp & File Number

For corners in

MENOMINEE  
(County)

Located In:

Corner Code #

- |                                    |                           |            |
|------------------------------------|---------------------------|------------|
| 1. Public Land Survey              | T <u>37N</u> R <u>25W</u> | <u>L-3</u> |
|                                    | T _____ R _____           | _____      |
|                                    | T _____ R _____           | _____      |
|                                    | T _____ R _____           | _____      |
| 2. Property Controlling in Section | S _____ T _____ R _____   | _____      |
|                                    | S _____ T _____ R _____   | _____      |
| 3. Miscellaneous Property in Sec.  | S _____ T _____ R _____   | _____      |
|                                    | S _____ T _____ R _____   | _____      |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Oct 29, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1853: Original Survey by George Adair - B.T.'s - Tamarack, 12" - S85°E, 13 lks; Cedar, 10" - N85°W - 19 lks. No original evidence found.
- 1968: L.C.R.C. No. 673-Vol 3 by Frank J. Bray, DNR Surveyor, states that a 1" dia. Iron Pipe/4" dia. Alum. cap was set midway and on line between section corners. B.T.'s - 8" Cedar - S47°E, 7.5 lks; 10" Cedar - S69°W - 16 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" dia. Iron Pipe/4" dia. Alum. cap and 2 Bearing Trees as described in part "A". The B.T. S47°E, 7.5 lks (4.95 feet) was found in good condition. We placed a nail in the side of this B.T. and re-used it. Since the DNR distance was to the face of the tree, our distance turns out to be 5.16 feet instead of 4.95 feet. The B.T. S69°W, 16 lks (10.56 feet) has been uprooted. Our measured distance West from this corner to the SW Corner (2599.41 feet) fits very closely with the GLO distance of 39.41 chains (2601.06 feet) We accepted the DNR Monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted existing 1"dia. Iron Pipe/3-1/4" dia. Alum. cap stamped for corner location:

6" dia. Cedar	N67°E	13.12 feet	Scr. NBT
9" dia. Cedar - (Ex. B.T.)	S47°E	5.16 feet	Scr. NBT
10" dia. Cedar	S72°W	18.74 feet	Scr. NBT
6" dia. Cedar	N26°W	13.66 feet	Scr. NBT
Survey Sign Post	N30°E	1.4 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca Date Nov. 15, 1994

Surveyor's Michigan License No. 26461

Nov. 15, 1994

