

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 37N N. S., R. 27W E. W.	A-5, A-6, A-7
2. PROPERTY CONTROLL- ING IN SECTION_____	T. _____ N. S., R. _____ E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ N. S., R. _____ E. W.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, David B. Babbitt, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on August 28, 1984, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-5	A-6	A-7
NW Sec. Corner of Sec. 18	West 1/4 Cor. of Sec. 18	SW Sec. Cor. of Sec. 18
Wood post	Wood post	Wood post
Lynn 14-N39W-40 Lks.	Tamarack 8 S27°W .03 chains	Hemlock 10"-S36W-15 Lks.
Sugar 14-S67W-20 Lks.	Cedar 8 N28°W .08 chains	" 16"-N33W-48 Lks.
W. Birch 18-N25E-34 Lks.		" 14"-N47E-52 Lks.
Lynn 18-S70E-26 Lks.		" 12"-S58E-58 Lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-5	A-6	A-7
Set by single proportionate measurement between the W1/4 Cor. of Sec. 18 and the NW Sec. Cor. of Sec. 7	Set from OBT stump, cedar 8N28W .08, Notch & scribing plainly visible. OBT, tamarack 8 S27W .03 In place, down and in very poor cond.	Set at very old fence cor. measurements south for 1 mile & east 1/2 mi. are consistent w/other measurements in this Twp. MEA north for 1/2 mile to a 1/4 Cor. Mon. set from an OBT Stp.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-5	A-6	A-7
1" pipe 4" alum. cap.	DNR Mon.	DNR Mon.
5" W. Birch S09°W 7.3'	5" Tamarack S73°E 12.55	10" maple - S68°E - 69.95'
5" Sug. Maple S84°W 19.0'	9" Cedar S38°W 6.8	5" maple - N18°E - 80.1'
5" " " N09°W 19.5'	6" Tamarack S80°W 4.65	3" spruce - N57°W - 67.8'
9" Lynn N26°E 20.8'	5" Cedar N30°E 13.0	8" poplar - N80°W - 55.9'

(over)

SIGNED BY

*David B. Babbitt*

DATE

*9-12-84*

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: