Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of

		P.A. Of 1990 On	2/27 1996
LAND CORNER RECORDATION		Mad	Jour RLS
For corners in Filling Requirement of Act 74, M	лісп. Р.А. 19/U	Cha	irmaq
MENOMINEE Located in: Corner Code #		`	
(County) Located in: Corner Code #		group a warp ag	
1 Public Land Currou		1-126	8 #
1. Public Land Survey T37N R 25W H01 T R			RECEIVED FOR
T38 RAS (H-13)		- Fig. 2	C S VEU
TR			õ
2. Property Controlling S T R		©	Marine.
in Section SR		1450で	# E
Property in Sec. S T R		~ 883	
	Reg	jister of Deeds Sta	mpi& File Number
4 Lethie Box 1 1804			
4. Lot No, Recorded Plat	АВ	CDEFG	HIJKL
	- ¹[Ţ		*
SAME AS CORNER H-13, T3BN-R25W	2 - 6	5 4 4	_311-
I, William Lenca , in a field survey on Aug. 20, 19 96 do hereby s	3		
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2	above were in	- N 8 - 1 - 9 - 1	-10-11-12-
conformance with regulations and rules therefore as required in the current manual of survey inst	ructions of the 5		
United States Department of the Interior, Bureau of Land Management or by a decree of a Court that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules o	of Law and /or 618	17: 16-	-15-1413-
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established	monumented, 7		
recovered, found as expressed below:	8 -1,9	20-21-	_222324_
NOTE: Not more than 2 comers, all in the same town and range, may be recorded	9		
on this certificate.	10—30	29 28	272625-
	11		
	12—31-	32 33	343536
	13		
A. Description of original monument and accessories and/or subsequent restoration			
 Original Survey by James H. Mullett - B.T.'s - White Pine, 10" - Noriginal evidence for this corner has been destroyed by county road in 1981: Certified Survey No. 226, recorded by William Lenca, RLS No. 2644 Section 34, T38N-R25W. The corner monument is described in the 	improvements. 61. shows this corner a	as it relates to othe	
B. Description of corner evidence found and/or method applied in restoring or reest			. 74
We recovered a 3/4 inch diameter iron pipe 18 inches long in the centerline of within 1.6 feet of splitting the mile between the Northwest Corner (G-1) and This corner has been used and accepted by local surveyors for at least 15 year position of the original corner.	the Northeast Corner (I-1) of Section 3	T37NLD25W
C. Description of monument for corner and accessories established to perpetuate location Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in	cating the position of the Monument Box:	e corner:	SURVEYOR # No. 26461
9" dia. Tamarak	N44 ^o E 96.67 feet	t Scr. NBT	Canada Car
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	S39°E 58.16 feet		
8" dia. Cedar	S40°W 54.58 feet		
8" dia. Balsam	N78 ^o W 79.79 feet		
Mctal Survey Sign Post	S39 ^o E 58.7 feet		
NOTE: All bearings are magnetic bearings. All distances are measured with	steel tape. Distances	to trees are to nail	in side of tree.
10 3 M 1	Dec. 26, 19	196	
Signed by William Frica	Date		
Surveyor's Michigan License No. 26461			