## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

for corners in

Menominee (County)	_ Located In:	Corner Code #					
1. Public Land Survey	T 41N R 26W T 41N R 26W	H03					
2. Property Controlling n Section	S T R S T R						
3. Miscellaneous Property in Sec.	S T R S T R		Register of D	Deeds Stamp & F	ile Number		
4. Lot No, Rec 5. Private Claims	corded Plat		A B C D	E F G H	IJKLM		
	8/05/201	4	2 5-5-	+-43-	<b>+</b> -2-1-1-1		
, Jeremy J. Pipp , in	a field survey on 8/05/201	4 do hereby state	3	++++	<del>                                     </del>		
hat under requirements of P.A. 7 bove were in conformance with r	74, Michigan P.A. of 1970, the corner poregulations and rules therefore as required	d in the current manual of survey	,5	9 10	12 12		
nstructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13 15 16 15 17 16 15 17 16 15 17 16 15 17 16 15 17 17 16 17 17 18 17 18 17 18 18 18 18 18 18 18 18 18 18 18 18 18							
	f of Land Surveyors or by a Decree of			-2122-	23 24		
NOTE: Not more than 2 corners on this certificate.	ers, all in the same town and range,	may be recorded	10 30 29 11 12 31 32	33 34	35 36		
4. Description of original mo	onument and accessories and/or so	ubsequent restoration:	13	<u> </u>	<del></del>		

- (HO3) Quarter corner common to Sections 3 and 10. 1852: E.C. Martin, DS. Set quarter section post witnessed by Tamarack 12 S60E 28 links (18.48'), Cedar 8 N53W 8 links (5.28'). 1951: Michigan DNR (Dean DeLameter PS#5778) Set 1" pipe with 4" Brass cap from original evidence witnessed by 8" Tamarack S60E 28 links (18.48'), 8" Cedar S30W 10 links (6.60').
- (IO2) Quarter corner common to Sections 2 and 3. 1852: E.C. Martin, DS. Set quarter section post witnessed by Tamarack 14 S74W 32 links (21.12'), Tamarack 12 N80E 24 links (15.84'). 1952: Michigan DNR (Dean DeLameter PS#5778) Set 1" pipe with 4" Brass cap from original evidence witnessed by 6" Spruce N53W 15 links (9.90'), 8" Cedar S77E 22 links (14.52').
- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (HO3) Accepted found MDNR Monument, trace remains of mound at OBT location SE, and Two NBT Nitnesses (NW face and trace scribing dead and down; SW tip out dead and down). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.
- (IO2) Accepted found MDNR Monument and One NBT Witnesses (SE in good condition). Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

• •						
6" Tamarack	N12E	15.26	(1/4S,NBT)			
17" Cedar	S51E	31.321	(1/4S,NBT)			
14" Cedar	S16W	21.86'	(1/4S, NBT)			
13" Cedar	N46W	15.76'	(1/4S,NBT)			
All trees are b	lazed,	scribed	d, painted,			
and signed. Measurements are to nail in						
side of tree, bearings are magnetic. A						
Metal sign post was set North 1.5 feet.						
Simpod by	(	1	1 1			

DNR monument

6" Cedar N41E 21.35' (1/4S, NBT) S86E 15.34' (1/4S,NBT) EX 8" Cedar \$48W 22.88' (1/48,NBT) 5" Cedar 7" Cedar 8.67' (1/4S,NBT) N44W All trees are blazed, scribed, painted, and signed. we asurements are to nail in ora ings are magnetic. A side a P

DNR monument

Meta et North 1.5 feet.

REMY Date August 25, 2014

Surveyor's Michigan License No. For the Michigan Department of Natural Resources

(102)

20414

TATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975 Revised Jan., 1983 Rervised Oct., 1995

(H03)